

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0003	5855015218616	SL-3-11046A	None of this equipment is classified as sensitive.	This is electronic gear and should not be agriculturally washed.	None	Same as configuration used OCONUS.
12	MCS C-PMM-122-ADM	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A0004	5999010321692	SL-3-07960A	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	None	N/A
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	Yes	A0007	5820015313493	DP 11126A 131 111260 00 Jul 2010 - no SL-3 found in TFSMS or on the Pubs Website. The listed document is for the disposal plan. The items listed by part number and cage in block W are accurate.	All hard drives will be removed and maintained by the owning unit prior to shipment of any Rover for repair/return. If the removed hard drive contains classified information it will be stored IAW procedures contain within the EKMS-1 manual and local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hard will be coordinated between the owning unit and the MARCORSYSCOM Project Office.	DO NOT POWER WASH. Use lint free cloth, paint brush and/or compressed air to clean this TAMCN and its equipment.	Message Traffic and a formal Disposal Plan have been published for this TAMCN	This item is being disposed of. No configuration for fielding required.
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	Yes	A0007	5895015624190	DP 11126A 131 111260 00 Jul 2010 - no SL-3 found in TFSMS or on the Pubs Website. The listed document is for the disposal plan. The items listed by part number and cage in block W are accurate.	All hard drives will be removed and maintained by the owning unit prior to shipment of any Rover for repair/return. If the removed hard drive contains classified information it will be stored IAW procedures contain within the EKMS-1 manual and local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hard will be coordinated between the owning unit and the MARCORSYSCOM Project Office.	DO NOT POWER WASH. Use lint free cloth, paint brush and/or compressed air to clean this TAMCN and its equipment.	Message Traffic and a formal Disposal Plan have been published for this TAMCN	This item is being disposed of. No configuration for fielding required.
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	Yes	A0008	5895015313135	FP 2050/1	N	N	There are no systems in theater. Five systems currently at Albany and the remaining systems are at Rockwell Collins for refurbishment and upgrade to NSN-5895015766176.	

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	Yes	A0008	5895015766176	FP 2050/1	N	N	There are no systems in theater. Five systems currently at Albany and the remaining systems are at Rockwell Collins for refurbishment and upgrade to NSN-5895015766176.	
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0009	5895012527359	SL-3-08629A	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	DP09090A awaiting PM signature. Disposal actions to begin 3rd Qtr FY12.	N/A
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0009	5895012509557	SL-3-08629A	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	None	N/A
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A0012	6130014952839	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	None	None	N/A
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A0012	6130014997305	NA	UNKNOWN	UNKNOWN	None	UNKNOWN
PEO LS	PEOLS-CAC2S	Tom Stevenson	15-Nov; 1430 - 1600	No	A0013	7010015346283					
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0015	5836090004317	SL-3-11199A	None of this equipment is classified as sensitive; however, the computer hard drive should be removed and retained until return to the using unit.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
14	MCS C-PMM-141	Anthony Smith & Dell Murray	14-Nov; 1500 - 1730	Yes	A0016	1290999580742	SL-3-11138A	None of this equipment is classified as sensitive.	LRU's can be washed but need to be air dried	None	N/A
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	Yes	A0019	5820013788778	TROPO (TCS)	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Use no water. Clean radios and components in accordance with technical manuals. Cleaning instructions can be found in the Tech Manual - TO 31R2-2GRC239-1	None	N/A
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0021	5895015128683	SL-3-10987A 123 109870 00 May 2011	The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager. 100% of all SSRI and UURI is to be shipped back to owning unit. MIDS LVT 11 5821-01-547-7436. Prior to shipping remove lithium batteries then ship IAW DOD 4160-21M and TB 43-0134, TSEC/KIV-7H5 or KIV-7M 5810-01-431-8264; TSEC/KG40A 5810-01-016-8052; 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH INSIDE OF SHELTER. Interior of shelter contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. The exterior of the shelter plus the HMMWV may be power washed.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0023	5895014457200	SL-3-10723A 123 107230 00 Jan 2006	The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager. 100% of all SSRI and UURI is to be shipped back with the end item. 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Item contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, follow the instructions in the Phase Out Plan. A WIR must be submitted, the item sent to Crane for inspection and then level A packaged for long term storage at MCLB Albany.	After all equipment has been inspected and repaired at Crane, the code A SL-3 complete asset will be level A packaged and placed into long term storage at MCLB Albany IAW the Phase Out Plan.
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0023	5895014773614	SL-3-10723A 123 107230 00 Jan 2006	The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager. 100% of all SSRI and UURI is to be shipped back with the end item. 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Item contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, follow the instructions in the Phase Out Plan. A WIR must be submitted, the item sent to Crane for inspection and then level A packaged for long term storage at MCLB Albany.	After all equipment has been inspected and repaired at Crane, the code A SL-3 complete asset will be level A packaged and placed into long term storage at MCLB Albany IAW the Phase Out Plan.
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0024	5895014773619	SL-3-10723A 123 107230 00 Jan 2006	The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager. 100% of all SSRI and UURI is to be shipped back with the end item. 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Item contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, follow the instructions in the Phase Out Plan. A WIR must be submitted, the item sent to Crane for inspection and then level A packaged for long term storage at MCLB Albany.	After all equipment has been inspected and repaired at Crane, the code A SL-3 complete asset will be level A packaged and placed into long term storage at MCLB Albany IAW the Phase Out Plan.

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	MCS-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0025	1430014079647	SL-3-10200A 123 102000 00 Nov 2010	No sensitive items contained in this TAMCN 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH INSIDE OF SHELTER. Interior of shelter contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. The exterior of the shelter plus the HMMWV may be power washed.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
16	MCS-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	A0026	6665013476100	SL-3-11336A	None of this equipment is classified as sensitive. No SSRI should be disassociated from the system. System should be returned SL-3 complete (minus batteries) SL-3-11336A	None	No	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0028	5895070001280	SL-3-11140B	The TAMCN is not classified as sensitive unless the is laptop has been used to store classified data. If the hard drive is marked classified, the using unit should remove the hard drive and retain it. A new hard drive can be obtained by CLS support after return from OEF. There are no specific procedures for disassociating the hard drive from the SECREP contained within the TAMCN.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0028	9999015314667	SL-3-11140B	The TAMCN is not classified as sensitive unless the is laptop has been used to store classified data. If the hard drive is marked classified, the using unit should remove the hard drive and retain it. A new hard drive can be obtained by CLS support after return from OEF. There are no specific procedures for disassociating the hard drive from the SECREP contained within the TAMCN.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A0029	5830015314687	TI-07737B-OR/TI 07737B-OD/2 No SI-3 associated to this TAMCN	All radios systems are controlled items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Recommendation: Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed
11	MCS-PMM-111	Richard Frank	17-Nov; 0900 - 1030	Yes	A0030	5895015799992	N/A	The TAMCN is not sensitive. Shipment of CCI equipment should be ship in accordance with EKMS procedures.	Nothing beyond standard procedures.	Currently there are three (3) M2C2 systems fielded to OEF in support of UUNS to fulfill capability gaps. M2C2 is a theater asset. System consist of one (1) A0030, four (4) A0386, thirteen (13) A0324 and one (1) Tactical Entry Point (TEP). Systems 2 & 3 fielded TEP A0325. System 1 fielded TEP ****	N/A: M2C2 was an interim solution. Transitioning to NOTM Inc 1 and fielding within the next two Fiscal Years (FY).
13	MCS-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	No	A0035	5845015314716	No SL-3	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial)	No	Obsolete replaced by the EoF-MM TAMCN C01047B. DP 5500 applies.	No configuration differences.
Not Assigned	MCS-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	A0036	5855015314664					
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0042	6720090004308	SL-3-11190A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
11	MCS-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A0043	5895015322062	N/A	This UUNS was initiated during OIF and completed years ago. It did not transition to a POR and is not supported by PG 11	This UUNS was initiated during OIF and completed years ago. It did not transition to a POR and is not supported by PG 11	This UUNS was initiated during OIF and completed years ago. It did not transition to a POR and is not supported by PG 11	This UUNS was initiated during OIF and completed years ago. It did not transition to a POR and is not supported by PG 11

PG	PMM	MCS POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0045	6130015322591	N/A	None	None	DP111788 Drafted. Disposal processing to begin in FY13. Disposal Plan is to be developed and published in the near term. Item exit date has expired and will not be extended.	None
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0057		system is obsolete	No Systems should be in OEF.	No Systems should be in OEF.	No Systems should be in OEF.	No Systems should be in OEF.
12	MCSC-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0059	6675090004321	TPC-OM-V.4.0	TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service. (Current authorized SSRI & UURI Configuration)
12	MCSC-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0060	5865090004327	SL-3-10444A	The unclassified system will be returned to the unit via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager.	DO NOT POWER WASH THE TRANSIT CASES. The transit cases contain sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After depot maintenance is completed, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI & UURI Configuration.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A0061	5985015494609	SL-3 11409	None of this equipment is classified as sensitive	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	N/A
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A0061	5985015678104	SL-3 11409	Refer to SL-3 inventory and Operators manual for SSRI/UURI. 100% of SSRI/UURI is to be returned with end item. TAMCN is a sensitive item. Transportation is to be completed IAW local SOP for shipment of sensitive items.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. Conduct all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0067	5820015336762	SL-3-11216A	Refer to SL-3 inventory and Operators manual for SSRI/UURI. 100% of SSRI/UURI is to be returned with end item. TAMCN is a sensitive item. Transportation is to be completed IAW local SOP for shipment of sensitive items.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. Conduct all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	MCSC-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0068	5820015340006	SL-3-11228B 123 112281 00 Jul 2011	No sensitive items contained in this TAMCN Ship 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Radio contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0069	5820015360983	SL-3-11247A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0069	6625013124134	SL-3-11247A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
10	MCSC-PMM-104	Kathy Embry	17-Nov; 0800 - 0900	Yes	A0079	7035015385759	N/A	COTS IT hardware and software. The TAMCN itself is not classified. TCWS Missions Assurance Category (MAC) is MAC Level II. TCWS has been assigned a Confidentiality Level (CL) of Classified when operating at the SECRET level, and a CL of Sensitive when operating at the Sensitive but Unclassified level. Any storage components within the system (hard drives and storage array) will be handeled IAW MCOs/directives.	N/A	A0079 is UUNS. A0079 will be replaced by A0342 FY12 at gaining command's home station.	N/A
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	A0081	6665014071237	SL-3-11323A	None classified or sensitive, There is no SL-3 for this system. Remove batteries prior to shipping	No	No	No
11	MCSC-PMM-112	Dave Schrumm	17-Nov; 0900 - 1030	No	A0082	5895014118466	No documentation found.	Not Applicable.	No. Unit normally remains in environmentally controlled shelter.	Item is Test Equipment/Computer Kit	
11	MCSC-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0086	4940013982615	Item has no documents listed in TFSMS or on the Publications website. Item was inducted into the Corps in Feb 1996. Item was taken out of service in the early 2000s. No SL-3 or other documents located.	UURI Items - Radios are CCI items Ship to LOGCOM - DoDAAC MMSA01	Nothing beyond standard procedures.		
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0090	5820015306497	SL-3 11132A	No, TAMCN itself is not classified sensitive. Yes, SSRI or UURI items are classified sensitive. CRYPTO must have a NAVMC 1018 tag with PEI serial number, PEI shipped to, and PEI condition code. Classified Hard Drive must be removed and turned in to CMCC. When turned-in, CMCC must provide PEI, PEI serial number, and unit PEI/GBS is being shipped to so they know where to send the hard drives. GBS Hard Drive NSN: 7025-01-529-3589 SAC 1 (not a RIP item) Handle in accordance with EKMS 1B & 5A.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	All four cases should be shipped as a set/complete end item. There are 3 computers per GBS. So, receiving unit may be required to purchase 3 new Hard Drives at a cost of \$593.36 per hard drive. MILAIR is the preferred form of shipment.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	Yes	A0091	5895015674768	SL-3-11913A 123 119130 00 Jun 2011	All hard drives(Part No. 440-7138-001) will be removed and maintained by the owning unit prior to shipment of any VideoScout for repair/return. If the removed hard drive contains classified information it will be stored IAW procedures contain within the EKMS-1 manual and local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hard will be coordinated between the owning unit and the MARCORSYSCOM Project Office.	DO NOT POWER WASH. Use lint free cloth, paint brush and/or compressed air to clean this TAMCN and its equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	Yes	A0091	5998015853681	SL-3-11913A 123 119130 00 Jun 2011	All hard drives(Part No. 440-7138-001) will be removed and maintained by the owning unit prior to shipment of any VideoScout for repair/return. If the removed hard drive contains classified information it will be stored IAW procedures contain within the EKMS-1 manual and local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hard will be coordinated between the owning unit and the MARCORSYSCOM Project Office.	DO NOT POWER WASH. Use lint free cloth, paint brush and/or compressed air to clean this TAMCN and its equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	No	A0096	5865015534770	Not an SL-3 item	This TAMCN is not classified sensitive, no classified SSRI/UURI associated with this system. NOTE: When shipping a Chameleon system that cannot be zeroized due to software failure, broken switch or other failure, the system must be shipped classified as SECRET. See Colum G	Clean with dry rag or air blower; Do not use high pressure washer or submerge in water. System has many electronic components.	Please direct all inquiries to USMC CREW Program Office, Quantico or CREW Item Manager Graves-Reynolds CIV Judy A, judy.graves@usmc.mil, (229) 639-8283	System are obsolete/legacy and will not be fielded CONUS
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	No	A0096	5865015557913	Not an SL-3 item	This TAMCN is not classified sensitive, no classified SSRI/UURI associated with this system. NOTE: When shipping a Chameleon system that cannot be zeroized due to software failure, broken switch or other failure, the system must be shipped classified as SECRET. See Colum G	Clean with dry rag or air blower; Do not use high pressure washer or submerge in water. System has many electronic components.	Please direct all inquiries to USMC CREW Program Office, Quantico or CREW Item Manager Graves-Reynolds CIV Judy A, judy.graves@usmc.mil, (229) 639-8283	System are obsolete/legacy and will not be fielded CONUS

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	No	A0096	599801DTQC044	Not an SL-3 item	This TAMCN is not classified sensitive, no classified SSRI/UURI associated with this system. NOTE: When shipping a Chameleon system that cannot be zeroized due to software failure, broken switch or other failure, the system must be shipped classified as SECRET. See Colum G	Clean with dry rag or air blower; Do not use high pressure washer or submerge in water. System has many electronic components.	Please direct all inquiries to USMC CREW Program Office, Quantico or CREW Item Manager Graves-Reynolds CIV Judy A, judy.graves@usmc.mil, (229) 639-8283	System are obsolete/legacy and will not be fielded CONUS
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0097	5820015659999	SI-311496A SL-3-11619A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0100	7030015737801	N/A	None of this equipment is classified as sensitive.	You can wash the Pelican case; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	CI/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS C-PMM-122-ADM	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A0104	5820015084395	N/A	None	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B	None	None
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	A0107	6130200022433	SL-3-11667C(PCN 123 116672 00)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	A0107	6130200049349	N/A	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
14	MCS C-PMM-141	Anthony Smith & Dell Murray	14-Nov; 1500 - 1730	No	A0116	6675015154610	SL-3-11138A	No, None	No direct water contact on electrical components	None	N/A
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0117	5895015698814	NO SL-3 published	None	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	N/A

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0118	5820015450334	SL-3-11372A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0118	5820015456349	SL-3-11372B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0118	5820015456358	SL-3-11372C	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0118	5820015487056	SL-3-11372A, SL-3-11372B, SL-3-11372C This is the RT associated with A0118.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
11	PMA263	Dave Schrumm	17-Nov; 0900 - 1030	Yes	A0121	1550015610012	SL-3-11561A PCN 123 115610 00	All hard drives will I remain with the Equipment for repair/return. If the hard drive contains classified information it will remain maintained by the owning unit be stored IAW procedures contain local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hardware will be coordinated between the owning unit and the NAVAIRSYSCOM Project Office.	DO NOT POWER WASH. Use damp rags and compressed air to clean this TAMCN and its equipment.	PMA-263 has the cog for this item. POC is Capt. Steven M. Stepanic PMA-263 Raven B and WASP Lead at (301)757-1796. Please direct inquiries about this item to PMA-263.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0122	5895015427716	SL-3-11358A	N/A	N/A	There are no NSN: 5895015427716 in the Marine Corps Inventory.	N/A

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0122	5895015625632	SL-3-11358A	No, TAMCN itself is not classified sensitive. Yes, SSRI or UURI items are classified sensitive. CRYPTO must have a NAVMC 1018 tag with PEI serial number, PEI shipped to, and PEI condition code. Handle in accordance with EKMS 1B & 5A.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B & 5A.	Do not separate weapon system from HMMWV. Use care when maneuvering system to not damage the reflector panel. It is made out of carbon fiber and very delicate. Ship via MILAIR. Reflector repair costs are estimated at and could potentially exceed \$100,000. *If mission capable, then (1) I MEF / 9th Communication Battalion (1) II MEF / 8th Communication Battalion **If non-mission capable, WIR to L-3.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0124	5895015439861	SL-3-10139A & SL-3-11332A	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	None	None
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0125	5895015439738	SL-3-10139A & SL-3-11333A	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	None	None
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0126	5820015377562	SL-3-11255A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0126	5820015659629	SL-3-11255B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0129	5820015549530	SL-3-11622A This NSN is associated to the RT for A0129. It is not the PEI.	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0129	5820015660746	SL-3-11622A	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0130	5895015704775	No SL-3 published	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	N/A
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0132	5895015439865	SL-3-10139A	KIV-19, TAMCN A8085, Qty 4 need to be WIRed via WOLPH to the EKMS manager. POC is Judy Reynolds. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	None	None
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0134	5820015437811	WPPL (TCS)	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0134	5820015437816	WPPL (TCS)	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0134	5895015449175	WPPL (TCS)	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.	Follow in accordance to the Disposal Plan reference DP 11348.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0136	5895015677085	N/A	No crypto or classified sensitive items associated with SWAN Hub.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*Systems to be sent to OEM for refurbishment and reissue to units. MCSC to fund on existing contract. MCLC will submit WIR to the IM.	MCLC Fwd conduct inventory by using SWAN Hub Inventory.xls and then conduct operation check. See Parts List PDF and Inventory List XLS. See PPT for configuration of SWAN Hub.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	No	A0137	5820015545423	Not an SL-3 item	This TAMCN is not classified sensitive, no classified SSRI/UURI associated with this system. NOTE: When shipping a system that cannot be zeroized due to software failure, broken switch or other failure, the system must be shipped classified as SECRET.	Clean with dry rag or air blower; Do not use high pressure washer or submerge in water. System has many electronic components	Please direct all inquiries to USMC CREW Program Office, Quantico or CREW Item Manager Graves-Reynolds CIV Judy A, judy.graves@usmc.mil, (229) 639-8283	System are obsolete/legacy and will not be fielded CONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0138	5895090004453		TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service. (Current authorized SSRI & UURI Configuration)
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0139	5820015419208	SL-3-11305A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31 Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications are complete.
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	Yes	A0141	5895015427911	N/A			This TAMCN should be removed from the Playbook. It is a compilation of TAMCNs that CD&I (LtCol McKay) has determined is too difficult to track as 1 TAMCN. All TAMCNs will be accounted for individually and are a part of the Playbook.	
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	Yes	A0142	5895015427735	FP 2050/1	KG-175 TAFLANE NSN 5810-01-463-0133 ID Nu 10672A needs to be W/Red via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy	None	DP11137 PCN 13158950100. This TAMCN is in the process of Disposal.	N/A
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0145	662501W00F262	None available				
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0147	5810090004482		TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service. (Current authorized SSRI & UURI Configuration)

PG	PMM	MCS POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0149	5985015410767	SL-3-11381A	No, TAMCN itself is not classified sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	Ensure embarkation specialist utilizes the Technical manual for proper tie down procedures. Any cargo straps place over the main reflector will cause damage rendering the system non-mission capable. Do not move with stabilizing wheel in position. Ship via MILAIR. Reflector repair costs are estimated at and could	N/A
10	MCSC-PMM-103	Lawrence Quirindongo - Dial In	17-Nov; 0800 - 0900	No	A0150	7010015561720	N/A	N/A	No		N/A
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0152	6720015868004	In development process - expect SL-3 completion in 3rd Qtr FY12. Please see amplifying comments cell for interim parts list.	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0153	5820015456691	SL-3-11305A	Prior to turn in for shipment the radio set must be "Zeroized" by an MOS 06XX Radio Operator in accordance with security regulations. Cryptographic equipment used with this radio set must be returned to the EKMS custodian prior to turning in the radio.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	N/A
PM MRAP	MCSC-PMM-154	Mark Billow - Dial In	14-Nov; 0900 - 1000	Yes	A0156	5836015450098	Draft SL-3 at Albany for review and publishing	This TAMCN is not classified as sensitive. There is no SSRI or UURI items that are classified sensitive. This equipment in its entirety should be shipped to MCLB Albany.	Power washing may be completed on the exterior (outside) only of this item. DO NOT POWER WASH INTERIOR COMPONENTS; contains sensitive electronics which water can damage. Use compressed air.	Upon MCLB Albany Receiving equipment from theater, PM-CIED should be contacted so a complete inventory assessment can be performed to ascertain the equipments reliability status. POC: Mr. Mark J. Billow, PM-CIED, (703) 462-4961.	This equipment is not a program of record and is not owned by any using unit. Therefore no configuration for fielding is required.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0168	5895015453002	SL-3-11404A	None of this equipment is classified as sensitive.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0168	5895090004458	SL-3-11404A	None of this equipment is classified as sensitive.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
11	MCSC-PMM-112	Dave Schrumm	17-Nov; 0900 - 1030	Yes	A0169	5840015418783	SL-3-111652A PCN 123 116520 00	None of this equipment is classified as sensitive.	The LCMR is an electronic piece of equipment and should not be washed. It can be cleaned by hand, by trained personnel.		
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0170	5895014955980	TM 11-5895-1708-12&P	TACLANE Network Encryption Device is UURI and must be disassociated from the A0170 using local SOP.	Do not power wash as this is electronic equipment. Use damp rags and compressed air to clean this TAMCN and its equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory, notify PG-12/PMM123 for maintenance, and coordinate shipment to appropriate RSC with MARCORSSYSCOM. Please direct inquires about this system to Commander, MARCORSSYSCOM, PM-Intelligence Systems, ATTN: SCI Comms Project Officer, 2200 Lester Street, Quantico, VA 22134-6050.	After all equipment has been returned from maintenance or supply system, the Code A - SL-3 complete asset will be placed back into full service at the owning unit. Code A, SL-3 complete will be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0172	6130015460023	TM-2005-OI/1-CD Appendix D	No crypto or classified sensitive items associated with PM.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	Batteries do not constitute failure, replace upon receipt at new unit. *If non mission capable, then this TAMCN for DDS-R (NSN 6130-01-546-0023), should be consolidation of assets to obtain maximum complete Power Modules. This should be completed at ELMACOs or MCLC Fwd. Transport complete PMs to fill any home station shortfalls and DRMO in Theater remaining PMs.	MCLC Fwd conduct Inventory of PM using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D-12, D-13, and D-14. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0172	6130015652835	TM-2070-CD Appendix D	No crypto or classified sensitive items associated with PM.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	Batteries do not constitute failure, replace upon receipt at new unit. *If non mission capable, then this TAMCN for DDS-M (NSN 6130-01-565-2835), transport to fill MEF and then MEFs to fill any home station shortfalls.	MCLC Fwd conduct Inventory of Power Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 86-88. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.

PG	PMM	MCS POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0173	5810015460020	TM-2005-OI/1-CD Appendix D	KG-175 (KG-175B NSN 5810-014630133 for DDS-R and KG-175D for DDS-M NSN Pending) Qty 2 or KIV-7M Qty 2 needs to be W/Red via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. POC is Judy Reynolds.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-R (NSN 5810-01-546-0020), should be a consolidation of assets to obtain maximum complete Power Modules. This should be completed at ELMACOs or MCLC Fwd. Transport complete CSMs to fill any home station shortfalls and DRMO in Theater remaining PMS.	MCLC Fwd conduct Inventory of Communications Security Module using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D-3 through D-7. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0173	5810015681184	TM-2070-CD Appendix D	KG-175 (KG-175B NSN 5810-014630133 for DDS-R and KG-175D for DDS-M NSN Pending) Qty 2 or KIV-7M Qty 2 needs to be W/Red via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. POC is Judy Reynolds.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-M (NSN 5810-01-568-1184), transport to fill EDL and then MEFs to fill any home station shortfalls.	MCLC Fwd conduct Inventory of Communications Security Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 4-15. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0174	5895015460016	TM-2005-OI/1-CD Appendix D	No crypto or classified sensitive items associated with LSM.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-R (NSN 5895-01-546-0016), should be a consolidation of assets to obtain maximum complete LSMs. This should be completed at ELMACOs or MCLC Fwd. Transport complete Power Modules to fill any home station shortfalls and DRMO in Theater remaining PMS.	MCLC Fwd conduct Inventory of LAN Services Module using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D-21 through D-25. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0174	5895015682669	TM-2070-CD Appendix D	No crypto or classified sensitive items associated with LSM.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-M (NSN 5895-01-568-2669), transport to fill MEF and then MEFs to fill any home station shortfalls.	MCLC Fwd conduct Inventory of LAN Services Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 34-45. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0175	5895015466466	TM-2005-OI/1-CD Appendix D	SIPRNET Harddrives are handled in course with classified storage and transport. Transport back unit in possession. All SIPR HDs must be removed from the CM laptop PCs and consolidated in an appropriate secure storage container for MIL-AIR transport from OEF to CONUS with the using unit. NO SIPR HDs will be vehicle transported through Pakistan for surface nor air shipment for commercial cargo carriers. Recommend that all SIPR DSMs TAMCN A0197, SIPR ASM Server HDs TAMCN A0177, and SIPR CM Laptop HDs TAMCN A0175 be consolidated into a single or two appropriate shipping container for MIL-AIR transport from OEM to CONUS with the departing using unit.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	Batteries (Qty 2) do not constitute failure, replace upon receipt at new unit. *If non mission capable, then this TAMCN for DDS-R (NSN 5895-01-546-6466), should be a consolidation of assets to obtain maximum complete CSMs. This should be completed at ELMACOs or MCLC Fwd. Transport complete Power Modules to fill any home station shortfalls and DRMO in Theater remaining PMS.	MCLC Fwd conduct Inventory of Configuration Module using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D-26 and D-27. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0176	5895015460013	TM-2005-OI/1-CD Appendix D	No crypto or classified sensitive items associated with LEM.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	Batteries do not constitute failure, replace upon receipt at new unit. *If non mission capable, then this TAMCN for DDS-R (NSN 5895-01-546-0013), should be a consolidation of assets to obtain maximum complete LEMs. This should be completed at ELMACOs or MCLC Fwd. Transport complete Power Modules to fill any home station shortfalls and DRMO in Theater remaining Power Modules.	MCLC Fwd conduct Inventory of LAN Extension Module using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D 8-11. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0176	5895015725551	TM-2070-CD Appendix D	No crypto or classified sensitive items associated with LEM.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	Batteries do not constitute failure, replace upon receipt at new unit. *If non mission capable, then this TAMCN for DDS-M (NSN 5895-01-572-5551), should be returned with unit and fixed at ELMACOs.	MCLC Fwd conduct Inventory of LAN Extension Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 16-22. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0177	7010015460027	TM-2005-OI/1-CD Appendix D	SIPRNET Harddrives are handled in course with classified storage and transport. Transport back unit in possession. All SIPR HDs must be removed from the ASM servers and consolidated in an appropriate secure storage container for MIL-AIR transport from OEF to CONUS with the using unit. NO SIPR HDs will be vehicle transported through Pakistan for surface nor air shipment for commercial cargo carriers. Recommend that all SIPR DSMs TAMCN A0197, SIPR ASM Server HDs TAMCN A0177, and SIPR CM Laptop HDs TAMCN A0175 be consolidated into a single or two appropriate shipping container for MIL-AIR transport from OEM to CONUS with the departing	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-R (NSN 7010-01-546-0027), should be a consolidation of assets to obtain maximum complete ASMs. This should be completed at ELMACOs or MCLC Fwd. Transport complete Power Modules to fill any home station shortfalls and DRMO in Theater remaining Power Modules.	MCLC Fwd conduct Inventory of Application Server Module using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D-15 through D-18. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0177	7010015681206	TM-2070-CD Appendix D	SIPRNET Harddrives are handled in course with clasified storage and transport. Transport back unit in possession. All SIPR HDs must be removed from the ASM servers and consolidated in an appropriate secure storage container for MIL-AIR transport from OEF to CONUS with the using unit. NO SIPRs HDs will be vehicle transported through Pakistan for surface nor air shipment for commercial cargo carriers. Recommend that all SIPR DSMs TAMCN A0197, SIPR ASM Server HDs TAMCN A0177, and SIPR CM Laptop HDs TAMCN A0175 be consolidated into a single or two appropriate shipping container for MIL-AIR transport from OEM to CONUS with the departing	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capbale, then this TAMCN for DDS-M (NSN 7010-01-568-1206), should be returned with unit and fixed at ELMACOs.	MCLC Fwd conduct Inventory of Application Server Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 27-33. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.
11	MCS-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0180	5895015476773	SL-3-11399A 123 113990 00 May 2009	No sensitive items contained in this TAMCN Ship 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Item contains sensitive electronics, computer, and software which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCS-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0182	5835090004505	SL-3-11554A FP 11554A TI 10318C/11554A-OI	TAMCN is sensitive asset. Transportation is to be completed IAW local SOP for shipment of sensitive items.	None	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. Conduct all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit CORTC reporting.	TAMCN will be retired 12 months after TCAC 4.3 fielding. The TAMCN hardware configuration will not be supported after this date. The capability has been incorporated into A26347G.
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0183	5865090004485	N/A	None of this equipment is classified as sensitive.	You can wash the Pelican case; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0184	5865070001269	N/A	None of this equipment is classified as sensitive.	You can wash the Pelican case; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0186	5865070001270	N/A	None of this equipment is classified as sensitive.	You can wash the Pelican case; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0187	5865070001271	N/A	None of this equipment is classified as sensitive.	You can wash the soft-side case and the equipment stored within the case. Power wash not recommended.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0188	5865070001272	N/A	None of this equipment is classified as sensitive.	You can wash the Pelican case; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0189	5895070001277	N/A	None of this equipment is classified as sensitive.	None of this electronic equipment should be subjected to water washdown. This includes the case.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0193	5895070001279	N/A	None of this equipment is classified as sensitive.	You can wash the Pelican case; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	C/HUMIT Marines typically "carry" their equipment with them; should not be transported by Local Nationals due to the nature of the equipment - highly pilferable.	Same configuration as OCONUS

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	Yes	A0194	6650070001274 (USMC Stock Number)	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	The TAMCN itself is not sensitive. There are no SSRI and UURI items that are sensitive.	Prior to wash down system should be in stowed and/or shipping configuration with all connector caps installed. All system components require no special considerations for agricultural wash down. The system is designed to withstand wet environmental conditions.	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	Yes	A0194	6650090004488 (USMC Stock Number)	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	The TAMCN itself is not sensitive. There are no SSRI and UURI items that are sensitive.	Prior to wash down system should be in stowed and/or shipping configuration with all connector caps installed. All system components require no special considerations for agricultural wash down. The system is designed to withstand wet environmental conditions.	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0194	6650090006502	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	The TAMCN itself is not sensitive. There are no SSRI and UURI items that are sensitive.	Prior to wash down system should be in stowed and/or shipping configuration with all connector caps installed. All system components require no special considerations for agricultural wash down. The system is designed to withstand wet environmental conditions.	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0195	7010015762585	SL-3-10848E	The unclassified system will be returned to the unit via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager. Refer to SL-3 for SSRI information. This systems has no UURI.	None. Water may damage system electronics	None	Systems requiring maintenance should be disposed of IAW disposal plan. Otherwise, systems retain existing SSRI configuration.
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0197	5895015924487	TM-2070-CD Appendix D	SIPRNET Harddrives are handled in course with classified storage and transport. Transport back unit in possession. *If 1 Harddrive is classified, all harddrives are classified. * All DSMs must be consolidated in an appropriate secure storage container for MIL-AIR transport from OEF to CONUS with the using unit. DO NOT remove the SIPR HDs as the whole DSM is classified. NO DSMs will be vehicle transported through Pakistan for surface nor air shipment for commercial cargo carriers. Recommend that all SIPR DSMs TAMCN A0197, SIPR ASM Server HDs TAMCN A0177, and SIPR CM Laptop HDs TAMCN A0175 be consolidated into a single or two appropriate shipping container for MIL-AIR transport from OEM to CONUS with the departing using unit.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-M (NSN 5895-01-592-4487), should be returned with unit and fixed at ELMACOs.	MCLC Fwd conduct Inventory of Data Storage Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 46-49. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0197	5895015494303	TM-2005-OI/1-CD Appendix D	SIPRNET Harddrives are handled in course with classified storage and transport. Transport back unit in possession. *If 1 Harddrive is classified, all harddrives are classified. * All DSMs must be consolidated in an appropriate secure storage container for MIL-AIR transport from OEF to CONUS with the using unit. DO NOT remove the SIPR HDs as the whole DSM is classified. NO DSMs will be vehicle transported through Pakistan for surface nor air shipment for commercial cargo carriers. Recommend that all SIPR DSMs TAMCN A0197, SIPR ASM Server HDs TAMCN A0177, and SIPR CM Laptop HDs TAMCN A0175 be consolidated into a single or two appropriate shipping container for MIL-AIR transport from OEM to CONUS with the departing using unit.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-R (NSN 5895-01-549-4303), should be a consolidation of assets to obtain maximum complete DSMs. This should be completed at ELMACOs or MCLC Fwd. Transport complete Power Modules to fill any home station shortfalls and DRMO in Theater remaining Power Modules.	MCLC Fwd conduct Inventory of Data Storage Module using TM 2005-OI/1-CD Appendix D, Marine Corps Stocklist pages D-19 and D-20. MCLC Fwd set-up DDS-R modules in accordance with TM 2005-OI/1-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0197	5895015653698	TM-2070-CD Appendix D	SIPRNET Harddrives are handled in course with classified storage and transport. Transport back unit in possession. *If 1 Harddrive is classified, all harddrives are classified. * All DSMs must be consolidated in an appropriate secure storage container for MIL-AIR transport from OEF to CONUS with the using unit. DO NOT remove the SIPR HDs as the whole DSM is classified. NO DSMs will be vehicle transported through Pakistan for surface nor air shipment for commercial cargo carriers. Recommend that all SIPR DSMs TAMCN A0197, SIPR ASM Server HDs TAMCN A0177, and SIPR CM Laptop HDs TAMCN A0175 be consolidated into a single or two appropriate shipping container for MIL-AIR transport from OEM to CONUS with the departing using unit.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*If non mission capable, then this TAMCN for DDS-M (NSN 5895-01-565-3698), should be returned with unit and fixed at ELMACOs.	MCLC Fwd conduct Inventory of Data Storage Module using TM 2070-CD Appendix D, Marine Corps Stocklist pages D 46-49. MCLC Fwd set-up DDS-M modules in accordance with TM 2070-CD Chapter 3 and power on according to Chapter 5, 5-3.
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0234	5895015504868	SL-3-11517A	No crypto or classified sensitive items associated with this TAMCN.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*Systems to be sent to OEM for refurbishment and upgrades and reissue to units. MCS C to fund on existing contract. MCLC will submit WIR to the IM.	MCLC Fwd conduct inventory of SWAN D v1 using SL-3 and TM 11517A-OR.
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0238	5895015515306	FP 2050	No crypto or classified sensitive items associated with spares package.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	Ship with SWAN D V3 to MCLC ALB for resale to Army. MCLC will submit WIR to the IM.	MCLC Fwd conduct Inventory using SL-3. MCLC Fwd conduct LTI/Operation Check by testing each individual spare items in the spares package. This will require use of laptop computer, and operational SWAN D V2.

PG	PMM	MCS POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0239	5895015514019	SL-3 11526A	No crypto or classified sensitive items associated with spares package.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	This TAMCN is a spares kit and will be shipped to MCLB Albany, Project Code PKA. LRUs will be disassembled at Albany and issued as IIP to the RIPS MCLC will submit WIR to the IM.	MCLC Fwd conduct Inventory using SL-3 11526A PCN 12311526000. MCLC Fwd conduct LTI/Operation Check by testing each individual spare items in the spares package. This will require use of laptop computer, power standard 110 with 20Amp breaker, operational SWAN D V1 or SWAN D V2, OOP File, SPECTRUM ANALYZER CAPABLE OF KU BAND OUTPUT, GROUND COMMON MULTI-METER, AND CABLE TEST SET, NSN: 6625-01-526-6476, PN: DSP-
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0240	5895015513812	SL-3 11525A	No crypto or classified sensitive items associated with spares package.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	This TAMCN is a spares kit and will be shipped to MCLB Albany, Project Code PKA. LRUs will be disassembled at Albany and issued as IIP to the RIPS MCLC will submit WIR to the IM.	MCLC Fwd conduct Inventory using SL-3 11525A PCN 12311525000. MCLC Fwd conduct LTI/Operation Check by testing each individual spare items in the spares package. This will require use of operational SWAN D Network Package, laptop computer and power standard 110 with 20Amp breaker.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0240	5895015686670	SL-3 11525A	No crypto or classified sensitive items associated with spares package.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	This TAMCN is a spares kit and will be shipped to MCLB Albany, Project Code PKA. LRUs will be disassembled at Albany and issued as IIP to the RIPS MCLC will submit WIR to the IM.	MCLC Fwd conduct Inventory using SL-3 11525A PCN 12311525000. MCLC Fwd conduct LTI/Operation Check by testing each individual spare items in the spares package. This will require use of operational SWAN D Network Package, laptop computer and power standard 110 with 20Amp breaker.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0241	5895015513530	SL-3-11523A	No crypto or classified sensitive items associated with SWAN D V2.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*Systems to be sent to OEM for refurbishment, upgrade and reissue to units. MCSC to fund on existing contract. MCLC will submit WIR to the IM	MCLC Fwd conduct inventory of SWAN D v2 using SL-3 and TM 11523A-OR.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0242	5895015805073	N/A (Not yet fielded)	KIV-7M needs to be WIred via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. POC is Judy Reynolds.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	None	Not fielded - Awaiting Fielding Decision .
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0242	5895015514320	FP 2050	KIV-7M needs to be WIred via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. POC is Judy Reynolds.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	TAMCN NSN 5895-01-551-4320 will be sold back to the Army. MCLC will submit WIR to the IM	
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0243	5895015513590	SL-3-11527A	KG175 Qty 1 needs to be WIred via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy Reynolds.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*Systems to be sent to OEM for refurbishment and upgrades and reissue to units. MCSC to fund on existing contract. MCLC will submit WIR to the IM.	MCLC Fwd conduct inventory of SWAN D v1 using SL-3 and TM 11527A-OR.
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0243	5895015686944	FP 2050/1	KG175 Qty 1 needs to be WIred via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy Reynolds.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	This NSN is being terminated and replaced by NSN: 5895015513590. MCLC will submit WIR to the IM	
12	MCSC-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0244	5895015513833	SL-3-11524A	No crypto or classified sensitive items associated with SWAN D MRT.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B.	*Systems to be sent to OEM for refurbishment and reissue to units. MCSC to fund on existing contract. MCLC will submit WIR to the IM	MCLC Fwd conduct Inventory using SL-3 11524A PCN 12311524000. MCLC Fwd conduct LTI/Operation check.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0245	5895015596098	DP11137 PCN 13158950100 - see amplifying comments	KG-175 TAFLANE NSN 5810-01-463-0133 ID Nu 10672A needs to be WIred via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy Reynolds.	None	DP11137 PCN 13158950100. This TAMCN is in the process of Disposal.	N/A
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0246	2840015877956		There are no SSRI or UURI items associated with this TAMCN.	Do not power wash as this is electronic equipment. Use damp rags and compressed air to clean this TAMCN and its equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory, notify PG-12/PM123 for maintenance, and coordinate shipment with MARCORSYSCOM for maintenance. Please direct inquiries about this system to Commander, MARCORSYSCOM, PM-Intelligence Systems, ATTN: SCI Comms Project Officer, 2200 Lester Street, Quantico, VA 22134-6050.	After all equipment has been returned from maintenance or supply system, the Code A - SL-3 complete asset will be placed back into full service at the owning unit. Code A, SL-3 complete will be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0247	2840015877961		None	None	None	None

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	Yes	A0254	5895015204341	SL-3 11032A	KIV-7HSB, TAMCN A8084, NSN: 5810-01-487-6582. Parent TAMCN is not classified sensitive. Item to be packaged and transported in accordance with the EKMS-1	The COC configuration includes many weather-resistant transit cases and two trailer types: the Operational Trailer (OT), consisting of an M1102 trailer with multiple transit-cased COTS IT components and electrical connections, and the Generator ECU Tent Trailer (GETT), consisting of an extended-bed M1102 chassis, a commercial 23kW generator, a commercial 120K BTU Environmental Control Unit, and a commercial Base-X 305 shelter. Care should be taken to avoid spraying water into/onto the OT's COTS IT equipment and the GETT's generator and ECU control panel. COC's are routinely shipped packed in an ISO container; recommend using ISO containers to ship the COC.		Reset systems are fielded in the most current configuration possible.
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	Yes	A0255	5895015204360	SL-3-11031A	KIV-7HSB, TAMCN A8084, NSN: 5810-01-487-6582. Parent TAMCN is not classified sensitive. Item to be packaged and transported in accordance with the EKMS-1	The COC configuration includes many weather-resistant transit cases and two trailer types: the Operational Trailer (OT), consisting of an M1102 trailer with multiple transit-cased COTS IT components and electrical connections, and the Generator ECU Tent Trailer (GETT), consisting of an extended-bed M1102 chassis, a commercial 23kW generator, a commercial 120K BTU Environmental Control Unit, and a commercial Base-X 305 shelter. Care should be taken to avoid spraying water into/onto the OT's COTS IT equipment and the GETT's generator and ECU control panel. COC's are routinely shipped packed in an ISO container; recommend using ISO containers to ship the COC.		Reset systems are fielded in the most current configuration possible.
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0261	7021090004486	SL-3-11457A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0266	5820015681631	SI-3-07737B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0266	5820015694438	SL-3-07737C	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	Yes	A0271	5895015573118	SL-3-11493A	KIV-7HSB, TAMCN A8084, NSN: 5810-01-487-6582. Parent TAMCN is not classified sensitive. Item to be packaged and transported in accordance with the EKMS-1	The COC(V)2 configuration includes many weather-resistant transit cases and the Operations Trailer (OT). The OT is an M1102 trailer with a rack supporting many COTS IT servers, routers, switches, etc. Care should be taken to avoid spraying water into/onto the OT's COTS IT equipment; recommend using ISO containers to ship the COC(V)2.		Reset systems are fielded in the most current configuration possible.

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A0272	5820015196016		All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed. NOTE: THE USMC DOES NOT HAVE THIS NSN IN THE INVENTORY.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A0272	5820015709290	SL-3-11686A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A0272	5895015627515	SI-11686A-OD	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0273	5820015578450	SL-3-11496A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0278	5820015631703	No SL-3 published	Controlled Cryptographic Items (CCI). Disposition of equipment identified as CCI will be the responsibility of the owning unit in accordance with current SL-3 requirements and T/E Allowances. If units no longer require these assets, disposition instructions for this equipment will be obtained using the following guidance:If this asset is no longer required for use by the unit, the unit should request disposition instructions from Director, Navy Communications Security Material System (NCMS) in accordance with the Electronic Key Management System (EKMS) -1 manual. The unit should also submit a TOECR to reduce the quantity of assets authorized.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	N/a

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0278	5820015836833	No SL-3 published	Controlled Cryptographic Items (CCI). Disposition of equipment identified as CCI will be the responsibility of the owning unit in accordance with current SL-3 requirements and T/E Allowances. If units no longer require these assets, disposition instructions for this equipment will be obtained using the following guidance: If this asset is no longer required for use by the unit, the unit should request disposition instructions from Director, Navy Communications Security Material System (NCMS) in accordance with the Electronic Key Management System (EKMS) -1 manual. The unit should also submit a TOECR to reduce the quantity of assets authorized.	Per: Armed Forces Pest Management Board Technical Guide NO. 31 Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0282	5825015293279	TM 11109A-OI, TM 11109A-OI/1, TM 11109A-OI/2, TM 11109A-OI/3, TM 11109A-OI/4, TM 11109A-OR	The TAMCN is not classified sensitive; however, the SSIMM-III is sensitive. Operational hard drives associated with this TAMCN are classified. It is the using unit's responsibility to maintain and transport those items. Follow local procedures for disassociation and disposal, if necessary.	Do not power wash as this is electronic equipment. Use damp rags and compressed air to clean this TAMCN and its equipment. Follow preventive maintenance procedures as listed in O&M TM 11109A-OI.	PG-12/PMM123 has situational awareness for this system. Please direct inquires about this system to Commander, MARCORSSYSCOM, PM-Intelligence Systems, ATTN: TPCS-MPC Project Officer, 2200 Lester Street, Quantico, VA 22134-6050.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	Yes	A0285	7010015221228	THIS TAMCN IS OBSOLETE	THIS TAMCN IS OBSOLETE	THIS TAMCN IS OBSOLETE	THIS TAMCN IS OBSOLETE	THIS TAMCN IS OBSOLETE
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	Yes	A0286	5840015874722	There are several subsystems associated with this TAM that currently have their own TAMCN. TAMCN Nomenclature Association B0730 MEP 831A (3kW gen) G-BOSS Lite A3255 MIDS All None MSTAR All TRSS Equipment: A3255 Unattended Ground Sensor All AN/GSQ-257 A1221 HHPM All AN/PSQ-22 A2306 Sensor, Mobile Monitor System All AN/MS C-77 A2300 Repeater Relay System All AN/GRQ-32 A3013 TRSS Maintenance Kit All	The TAMCN itself is not sensitive. There are no SSRI and UURI items that are sensitive.	Prior to wash down system should be in stowed and/or shipping configuration. All system components require no special considerations for agricultural wash down. The system is designed to withstand wet environmental conditions.	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	Yes	A0288	6350090006681 (USMC Stock Number)	There are several subsystems associated with this TAM that currently have their own TAMCN. TAMCN Nomenclature Association None MEP 501A (2kW 28 vDC gen) Cerberus Lite A3255 MIDS All None MSTAR All TRSS Equipment: A3255 Unattended Ground Sensor All AN/GSQ-257 A1221 HHPM All AN/PSQ-22 A2306 Sensor, Mobile Monitor System All AN/MS C-77 A2300 Repeater Relay System All AN/GRQ-32 A3013 TRSS Maintenance Kit All	The TAMCN itself is not sensitive. There are no SSRI and UURI items that are sensitive.	All system components require no special considerations for agricultural wash down. The system is designed to withstand wet environmental conditions.	There are several subsystems associated with this TAM that currently have their own TAMCN or will probably have one prior to IOC of Increment 2 of the G-BOSS (E) Acquisition Program. Examples of subsystems associated with this TAMCN that currently have their own TAMCN are the MEP generators and TRSS. Examples of subsystems associated with this TAMCN that will probably have a TAMCN in the future are COMM Suites, MSTAR Ground Radar, VideoScout, etc..	

PG	PMM	MCS C POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	No	A0291	5865015534738	Not an SL-3 item	This TAMCN is not classified as sensitive, no classified SSRI/UURI associated with this system. NOTE: When shipping a CVRJ system that cannot be zeroized due to software failure, broken switch or other failure, the system must be shipped classified as SECRET.	Clean with dry rag or air blower; Do not use high pressure washer or submerge in water. System has many electronic components	Please direct all inquiries to USMC CREW Program Office, Quantico or CREW Item Manager Graves-Reynolds CIV Judy A, judy.graves@usmc.mil, (229) 639-8283	System were provided as a capability to Theater; ownership of these system are the War Reserve Mateial Requirement (WRMR); systems operates in its complete configuratuon
10	MCS C-PMM-103	Mike McAuliffe - Dial In	17-Nov; 0800 - 0900	No	A0298	7025014759974	N/A	This TAMCN IS NOT classified sensitive. No SSRI or UURI items associated to this TAMCN.	None	None	None
10	MCS C-PMM-103	Mike McAuliffe - Dial In	17-Nov; 0800 - 0900	No	A0299	7490014759671	N/A	This TAMCN IS NOT classified sensitive. No SSRI or UURI items associated to this TAMCN.	None	None	None
10	MCS C-PMM-103	Mike McAuliffe - Dial In	17-Nov; 0800 - 0900	No	A0300	7490015589256	N/A	This TAMCN IS NOT classified sensitive. No SSRI or UURI items associated to this TAMCN.	None	None	None
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0301	7025014774041					
11	PMA263	Dave Schrumm	17-Nov; 0900 - 1030	No	A0321	1550015780205	SL-3-11796A PCN 123 117960 00	All hard drives will remain with the Equipment for repair/return. If the hard drive contains classified information it will remain maintained by the owning unit. be stored IAW procedures contain local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hardware will be coordinated between the owning unit and the NAVAIRSYSCOM Project Office.	DO NOT POWER WASH. Use damp rags and compressed air to clean this TAMCN and its equipment.	PMA-263 has the cog for this item. POC is Capt. Steven M. Stepanic PMA-263 Raven B and WASP Lead at (301)757-1796. Please direct inquiries about this item to PMA-263.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0325	5895015800008	N/A	The TAMCN is not sensitive. Shipment of CCI equipment should be ship in accordance with EKMS procedures.	Nothing beyond standard procedures.	This TAMCN is part of the M2C2 system see additional comments associated with TAM A0030.	N/A: M2C2 was an interim solution. Transitioning to NOTM Inc 1 and fielding within the next two Fiscal Years (FY).
12	MCS C-PMM-121	Karen Hartman, GySgt Hicks, & Bob Witherspoon	17-Nov; 1030 - 1800	Yes	A0326	5865015804854	Not an SL-3 item	This TAMCN is not classified sensitive, no classified SSRI/UURI associated with this system. NOTE: When shipping a system that cannot be zeroized due to software failure, broken switch or other failure, the system must be shipped classified as SECRET.	Clean with dry rag or air blower; Do not use high pressure washer or submerge in water. System has many electronic components	Upon returning from Theater units should conduct a complete detailed SL3 inventory. If any missing SL3 is note please contact the USMC CREW Product Support Intergartor at USMC CREW Product Support Operations Center, 4801 C Rivers Ave, Charleston, SC 29406 (843)414-5302 for sparing, maintenance	Thor III fielding was a "Total Packgae Fielding" units received completed suites at time of fielding. All systems returning from maintenance will be in Condition Code "A" and SL3 complete

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0331	5820015826675	SL-3-11863A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1). There are no SSRI or UURI items that are classified sensitive.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0336	5820015862327	SL-3-11927A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0338	6720015938038	SL-3-11192A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0339	6720015937979	SL-3-11193A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0340	5836015922160	SL-3-11195A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
13	MCS C-PMM-134	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	A0350	6350015910219		Nothing considered classified.	None	None	UUNS item to be allocated to contingency pool due to low quantity
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0351	5820015883075	SL-3-11971A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0352	5820015892203	SL-3-11990A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0357	5895015911110	SL-3-12016A				
PM MRAP	MCS C-PMM-154	Mark Billow - Dial In	14-Nov; 0900 - 1000	Yes	A0377	5840015995119	Draft SL-3 at Albany for review and publishing	This TAMCN is not classified as sensitive. There is no SSRI or UURI items that are classified sensitive. This equipment in its entirety should be shipped to MCLB Albany.	DO NOT POWER WASH; contains sensitive electronics which water can damage. Use compressed air.	Upon MCLB Albany Receiving equipment from theater, PM-CIED should be contacted so a complete inventory assessment can be performed to ascertain the equipments reliability status. POC: Mr. Mark J. Billow, PM-CIED, (703) 462-4961.	This equipment is not a program of record and is not owned by any using unit. Therefore no configuration for fielding is required.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
Not Assigned	MCS C-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	A0425	5895015220639					
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0501	7010090004208	TPC-OM-V.4.0	TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service. (Current authorized SSRI & UURI Configuration)
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0503	7010090004210	TPC-OM-V.4.0	TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service. (Current authorized SSRI & UURI Configuration)
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0504	6675013862679	SL-3-10077A	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0504	7010090004207	SL-3-10077A	TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service. (Current authorized SSRI & UURI Configuration)
12	MCS C-PMM-122-NET	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A0652	6020012372218	N/A	None	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	DP09006A. This TAMCN is in the process of disposal.	None
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0806	5895014959105	SL-3-10877A SL-3-10939A	No, TAMCN itself is not classified sensitive. Yes, SSRI or UURI items are classified sensitive. CRYPTO must have a NAVMC 1018 tag with PEI serial number, PEI shipped to, and PEI condition code. Handle in accordance with EKMS 1B & 5A.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	DO NOT SEPARATE transit cases, ship together. If one transit is missing the weapon system will be non mission capable. A0806 (V)1 = 5 Transit Cases. *If non-mission capable, then WIR ship to Commercial Depot as long as there is a contract in place. If there is no contract, then we bring them to MCLC ALB to hold until we have a contract.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A0807	5895014959106	SL-3-10878A SL-3-10939A	No, TAMCN itself is not classified sensitive. Yes, SSRI or UURI items are classified sensitive. CRYPTO must have a NAVMC 1018 tag with PEI serial number, PEI shipped to, and PEI condition code. Handle in accordance with EKMS 1B & 5A.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	DO NOT SEPARATE transit cases, ship together. If one transit is missing the weapon system will be non mission capable. A0807 (V)2 = 4 Transit Cases. *If non-mission capable, then WIR ship to Commercial Depot as long as there is a contract in place. If there is no contract, then we bring them to MCLC ALB to hold until we have a contract.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
14	MCS C-PMM-141	Anthony Smith & Dell Murray	14-Nov; 1500 - 1730	No	A0808	6675014677441	SL-3-10667A	No, None	N/A	None	N/A
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0819	7010090004281	N/A	No, None	N/A	This equipment should reside on the Using Units Consolidated Memorandum Receipt (CMR), each unit should have their own equipment.	N/A
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0872	5895014824470	N/A	No, None	N/A	This equipment should reside on the Using Units Consolidated Memorandum Receipt (CMR), each unit should have their own equipment.	N/A
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0872	5895015711777	N/A	No, None	N/A	This equipment should reside on the Using Units Consolidated Memorandum Receipt (CMR), each unit should have their own equipment.	N/A
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0872	5895090004283	N/A	No, None	N/A	This equipment should reside on the Using Units Consolidated Memorandum Receipt (CMR), each unit should have their own equipment.	N/A
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0873	5895014824634	SL-3-10752C	The unclassified system will be returned to the unit via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager. Refer to SL-3 for SSRI information. This systems has no UURI.	None. Water may damage system electronics	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and preventative maintenance assessment. Provide systems to CLS for all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	Following any required maintenance, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI Configuration.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0873	5895090004191	SL-3-10752C	The unclassified system will be returned to the unit via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager. Refer to SL-3 for SSRI information. This systems has no UURI.	None. Water may damage system electronics	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and preventative maintenance assessment. Provide systems to CLS for all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	Following any required maintenance, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI Configuration.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0873	5895090004424	SL-3-10752C	The unclassified system will be returned to the unit via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager. Refer to SL-3 for SSRI information. This systems has no UURI.	None. Water may damage system electronics	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and preventative maintenance assessment. Provide systems to CLS for all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	Following any required maintenance, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI Configuration.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0874	5895015806326	SL-3-11781A	The unclassified system will be returned to the Engineering Support Activity via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager. Refer to SL-3 for SSRI information. This systems has no UURI.	None. Water may damage system electronics	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and preventative maintenance assessment. Provide systems to CLS for all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	Following any required maintenance, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI Configuration.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A0874	7010090004323	SL-3-11781A	The unclassified system will be returned to the Engineering Support Activity via organic Marine Corps shipping. The COMSEC, CCI and computer hard drives need to be shipped IAW SOP and guidance from the EKMS manager. Refer to SL-3 for SSRI information. This systems has no UURI.	None. Water may damage system electronics	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and preventative maintenance assessment. Provide systems to CLS for all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	Following any required maintenance, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI Configuration.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0878	5895090000310	SL-3-10809A	TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0878	5895090004451	SL-3-10809A	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.	This NSN is obsolete and should have been previously disposed of. Any captured items will be disposed of by FSR IAW disposal instructions.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0879	5895015774129	SL-3-10809A	TAMCN is sensitive asset. Transportation is to be completed IAW local Security SOP for shipment of sensitive items.	DO NOT POWER WASH THE SYSTEM. The transit cases can be washed and dried completely prior to loading sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe the system clean and filters may be removed.	Upon receiving item from theater, owning unit needs to complete a detailed inventory and a detailed maintenance assessment.	After the FSR has completed the inventory and required maintenance, the system will be completely Op Checked for serviceability and placed back into full service.
11	MCS C-PMM-112	Dave Schrumm	17-Nov; 0900 - 1030	No	A0880	5895014605448	TM 10851A-12&P/B PCN 184 108510 00 No SL-3 located but the TM has a listing of the items in section 1-4	TAMCN classified CONFIDENTIAL. Remove sensitive CCA and lock in safe. Ensure UPX-37 locked in rack.	No. Unit normally remains in environmentally controlled shelter.	USN/PMA 213 is Program Manager for the UPX-37 Interrogator	
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A0882	5820014421073	SL-3-10370A 123 103700 00 Dec 2006	No sensitive items contained in this TAMCN 100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Item contains sensitive electronics, radios, computers, and software which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0886	5895015316021	SL-3-10834B	A8085, KIV-19A; A8084, KIV-7H; A8010, STE submit WIR via WOLPH to EKMS manager. POC is Judy Reynolds. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped to, PEI Condition Code	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B	None	None

PG	PMM	MCS POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A0892	5815014787095	N/A	None	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	None	None
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0904	5895014586392	N/A	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0904	5895090002099	N/A	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.	This TAMCN has been archived; all equipment has new TAMCNs (listed in this R2 playbook). Those instructions should be followed.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0905	5895014200425	SL-3-11198A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0905	6760090004316	SL-3-11198A				
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0907	6760090004309	SL-3-11191A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0908	6760090004315	SL-3-11197A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0909	5895090004314	SL-3-11196A	None of this equipment is classified as sensitive; however, the computer hard drive should be removed and retained until return to the using unit.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0910	5895090004307	SL-3-11188A	None of this equipment is classified as sensitive; however, the computer hard drive should be removed and retained until return to the using unit.	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A0918	5820013664120	SL-3-10191A This system has a disposal plan POP 10191A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
Not Assigned	MCSC-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	A0920	6150014353920					
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A0921	5895015036100	ULSS 001502-15	There are no SSRI or UURI items associated with this TAMCN.	Do not power wash as this is electronic equipment. Use damp rags and compressed air to clean this TAMCN and its equipment.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory, notify PG-12/PM123 for maintenance, and coordinate shipment to appropriate RSC with MARCORSYSCOM. Please direct inquires about this system to Commander, MARCORSYSCOM, PM-Intelligence Systems, ATTN: SCI Comms Project Officer, 2200 Lester Street, Quantico, VA 22134-6050.	After all equipment has been returned from maintenance or supply system, the Code A - SL-3 complete asset will be placed back into full service at the owning unit. Code A, SL-3 complete will be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	MCSC-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0932	7010014600494	N/A	N/A	N/A	This equipment should resides on the Using Units Consolidated Memorandum Receipt (CMR), each units should have their own equipment.	N/A
11	MCSC-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0932	7010015753698	N/A	N/A	N/A	This equipment should resides on the Using Units Consolidated Memorandum Receipt (CMR), each units should have their own equipment.	N/A
11	MCSC-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A0932	7010090000931	N/A	N/A	N/A	This equipment should resides on the Using Units Consolidated Memorandum Receipt (CMR), each units should have their own equipment.	N/A
12	MCSC-PMM-122-NET	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A1078	5820011452458	SL-3-08792A W/CH 1-4	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS-1B	Disposal Plan 08792A is published with disposal actions starting in 3rd quarter FY12.	None

PG	PMM	MCS POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A1214	5895011022100	SL-3-08229A	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	Disposal Plan 08229A is published with disposal actions starting in 3rd quarter FY12.	None
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A1220	5820015249479	TM 11063A	There are no SSRI or UURI items associated with this TAMCN.	DO NOT POWER WASH. Item contains sensitive electronics, radios, computers, and software which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of supply support needed.	After all equipment has been returned from maintenance or supply system, the Code A - SL-3 complete asset will be placed back into full service at the owning unit. Code A, SL-3 complete will be interpreted as the same condition as originally fielded plus any software/hardware
12	MCS-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A1221	7035015218607	SL-3-11045A	None of this equipment is classified as sensitive.	This is electronic gear and should not be agriculturally washed.	No	same as configuration used OCONUS
12	MCS-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A1225	5895090002382	SL-3-10901A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31 Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A1260	5825015168038	SL-3-09880C/09880D	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	DP in draft as of 10/11/11 All information for identified TAMCN A1260 is DAGR; PLGR is obsolete. Must be zeroized IAW TM 09880C-OR. Pack individually IAW MILSTD to avoid damage.	N/A
12	MCS-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A1260	5825015264783	SL-3-09880C/09880D	None of this equipment is classified as sensitive.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable.	All information for identified TAMCN A1260 is DAGR; PLGR is obsolete. Must be zeroized IAW TM 09880C-OR. Pack individually IAW MILSTD to avoid damage.	N/A
11	MCS-PMM-112	Dave Schrumm	17-Nov; 0900 - 1030	No	A1440	5840014506708	SL-3-08211D/08211E PCN 123 023360 00	No, Yes (SINGARS and EPLRS radios), Items need to be shipped via traceable means,	The Firefinder Radar is an electronic piece of equipment, High pressure hoses should not be used on the Antenna Transiever Group or the Shelter, no compartment should be opened while washing nor should the insides of the system be washed.	None	N/A
11	MCS-PMM-112	Dave Schrumm	17-Nov; 0900 - 1030	No	A1500	5840013550092	SL-3-07736C PCN 123 077362 00	Not Applicable.	The AN/TPS-63 Radar is an electronic piece of equipment, High pressure hoses should not be used on the Antenna or the Shelter, no compartment should be opened while washing nor should the insides of the system be washed.	None	N/A
11	MCS-PMM-112	Dave Schrumm	17-Nov; 0900 - 1030	No	A1503	5840014129653	SL-3-07751B PCN 123 077511 00	Not Applicable.	The AN/TPS-59 Radar is an electronic piece of equipment, High pressure hoses should not be used on the Antenna Transiever Group or the Shelter, no compartment should be opened while washing nor should the insides of the system be washed.	None	N/A
12	MCS-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A1520	5865014374914	LIN: T37036 TM-11-5865-348-10-1 no SL-3 this is ARMY Model Type taken from LORA Certification and TM: AN/TSQ-179 (V)2 TM-11-5865-1044-10 TM-11-5865-1044-23&P	The COMSEC, CCI, computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager to the owning unit. The Surveillance Control Data Link (SCDL) antenna should be returned to the unit, and if maintenance is required, inducted by the field service representative to Cubic Defense Systems for maintenance.	DO NOT POWER WASH INSIDE OF SHELTER. Interior of shelter contains sensitive electronics which water can damage. The system will be secured and should not be opened. Use compressed air and a vacuum to dust and clean any exterior areas. Damp rags may be used to wipe exterior areas clean. The exterior of the shelter plus the HMMWV may be power washed.	Upon receiving item from theater, Tobyhanna Army Depot needs to complete a detailed inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic depot level maintenance required.	After depot maintenance is completed, the system is placed back into full service and is returned to the owning unit. A completed inventory will be conducted and the removed CCI, COMSEC and computer hard drives will be replaced returning the system to original SSRI & UURI Configuration.

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A1818	5820013268947	SL-3-09780A 123 097800 00 Dec 1998	If the AN/GRC -171 is connected to the TSEC/KY-57 and TSEC/KY-58 the security of the radio will be in accordance with current directives. If the AN/GRC-171 (V)4 has three or more current or future operational Kal-9200 stored, it shall be treated as CONFIDENTIAL.100% of all SSRI and UURI is to be shipped back to owning unit with end item.	DO NOT POWER WASH. Radio contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A1956	5895013649337	SL-4-09771A No SL-3 Published	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A1957	5820013618536	No SL-3 published	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A1957	5820014318931	SL-3-09730B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A1958	5895013695560	SL-3-09786A	None	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCS C-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2042	5820014787615	SL-3-10532B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstal and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2042	5820014923628	SL-3-10822A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2042	5820014963523	SL-3-10822A This NSN is associated to the RT for A2042. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2043	5810014601607	. No SL-3 on file for NSN/TAMCN	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2043	5810090000353	SL-3-10745B	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2043	5820012868792	. No SL-3 on file for NSN/TAMCN	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2043	5820014601605	. No SL-3 on file for NSN/TAMCN	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.

PG	PMM	MCSC POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2044	5810090000354	SL-3-10746B	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2044	5820015729367	SL-3-10746C	Yes, the Controlled Inventory Item Code (CIIC) is "9". The R/Ts are considered "sensitive" and are controlled by the EKMS manager. Unit SOP determine SSRI/UURI disassociation procedures from the R/T. PHST procedures are described in the Fielding Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2065	5820010279071	SI-07748A/09214A-OD-1	Follow in accordance to the Disposal Plan	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Follow in accordance to the Disposal Plan	Follow in accordance to the Disposal Plan
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2068	5820014622484	SL-3-10597A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2068	5820015210291	This NSN is associated to the RT for A2068. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2070	5820012679482	SL-3-09669A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.

PG	PMM	MCSC POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2073	5820013636929	SL-3-09669B This NSN is associated to the RT for A2073. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2073	5820014210801	SL-3-09669B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2073	5820015353667	SL-3-09669B This NSN is associated to the RT for A2073. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2074	5820013521694	SL-3-09667B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2075	5820014206619	SL-3-09668B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2075	5820014441219	SL-3-09668B This NSN is associated to the RT for A2075. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.

PG	PMM	MCSC POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2075	5820015353667	SL-3-09668A / SL-3-09668B This NSN is associated to the RT for A2075. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2077	5820014206621	SL-3-09670A/ SL-3-09670b	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2078	5820014212605	SL-3-09471B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2079	5820014441219	SL-3-09669A /SL-3-09669B /SL-3-09669C This NSN is associated to the RT for A2079. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit need to complete a detailed SL-3 inventory and maintenance assessment this will show how much organic supply support needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2079	5820014518252	SL-3-09669C	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit need to complete a detailed SL-3 inventory and maintenance assessment this will show how much organic supply support needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2079	5820015353667	SL-3-09669A /SL-3-09669B /SL-3-09669C This NSN is associated to the RT for A2079. It is not the PEI.	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit need to complete a detailed SL-3 inventory and maintenance assessment this will show how much organic supply support needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.

PG	PMM	MCSC POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2152	5820014628411	SL-3-10656A /SL-3-10656C / SL-3-10901A ULSS-002498-15	Prior to turn in for shipment the radio set must be "Zeroized" by an MOS 06XX Radio Operator in accordance with security regulations. Cryptographic equipment used with this radio set must be returned to the EKMS custodian prior to turning in the radio.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	None	N/A
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	Yes	A2152	5820015141408	SL-3-10656B This NSN is associated to the RT for A2152. It is not the PEI.	Prior to turn in for shipment the radio set must be "Zeroized" by an MOS 06XX Radio Operator in accordance with security regulations. Cryptographic equipment used with this radio set must be returned to the EKMS custodian prior to turning in the radio.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2167	5820012679481	SL-3-09667A/	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2168	5820012679479	SL-3-09668A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2169	5820012685105	SL-3-09671A /SL-3-09671B	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2171	5820012679477	SL-3-09471A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCSC-PMM-124	Will Ponder & Rob Lewis	17-Nov; 1030 - 1800	No	A2179	5895015602957	SL-3-08658C /SL-3-08658D	Prior to turn in for shipment the radio set must be "Zeroized" by an MOS 06XX Radio Operator in accordance with security regulations. Cryptographic equipment used with this radio set must be returned to the EKMS custodian prior to turning in the radio.	Per: Armed Forces Pest Management Board Technical Guide NO. 31Thoroughly clean mount-out boxes/Hardigg-like cases, field desks, communications equipment, and similar items with hand brooms, rags, and other non-water methods. Compressed air may also be used. Specifically concentrate on cracks, crevices, and recesses. Also See the Technical Manual for uninstall and installation procedures. Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit complete a detailed SL-3 inventory and maintenance assessment. This will show how much organic supply support will be needed.	Recommend that all equipment be return from maintenance and entered into the supply system in condition Code A (same condition as originally fielded) plus any software/hardware upgrades or modifications have been completed.
11	MCSC-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A2293	5411013129084	SL-3-10393A 123 103930 00 Jun 2003	No sensitive items contained in this TAMCN. 100% of all SSRI/UURI is to be shipped back to owning unit.	Power washing may be completed on the inside and outside of this item. Care should be taken around power outlets and wiring to prevent damage. Unservicable outlets will be replaced during rebuild as well as the wiring.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A2300	5820014863797	SL-3-10789A	None of this equipment is classified as sensitive.	This is electronic gear and should not be agriculturally washed.	No	same as configuration used OCONUS
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A2306	6350013821826	TM 09856A-10/2C	The TAMCN is not classified as sensitive unless the is laptop has been used to store classified data. If the hard drive is marked classified, the using unit should remove the hard drive and retain it. A new hard drive can be obtained by CLS support after return from OEF. There are no specific procedures for disassociating the hard drive from the SECREP contained within the TAMCN. UURI classified as sensitive: ANDVT MINTERM, KY-99A (crypto gear) should be retained by the using unit until the unit returns to the home station.	The exterior of the vehicle can be powerwashed, but the electronic gear within the shelter should NOT be agriculturally washed. Should the electronic equipment within the TAMCN be powerwashed it would be ruined beyond economical repair and would have to be reprocedured.	Recommend no local nationals transport this gear as it contains equipment that is considered highly pilferable. (i.e COTS ITE)	same as configuration used OCONUS
11	MCSC-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A2333	5411012949866	SL-3-10394A 123 103940 00 Sep 2007	No sensitive items contained in this TAMCN. 100% of all SSRI/UURI is to be shipped back to owning unit.	Power washing may be completed on the inside and outside of this item. Care should be taken around power outlets and wiring to prevent damage. Unservicable outlets will be replaced during rebuild as well as the wiring.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	A2335	5411013046122	SL-3-09272A	No sensitive materiel All SL-3 should remain inside the shelter. Strap SL-3 down and secure in accordance with the designated load plan per TM 5411-14. SL-3-09272A	No	None	SSRI complete
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	A2336	5411013046121	SL-3-09271A	No sensitive materiel All SL-3 should remain inside the shelter. Strap SL-3 down and secure in accordance with the designated load plan	No	None	SSRI complete
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	A2337	5411013057366	SL-3-09281A	No sensitive materiel All SL-3 should remain inside the shelter. Strap SL-3 down and secure in accordance with the designated load plan	No	None	SSRI complete
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	A2338	5411013046123	SL-3-09273A	No sensitive materiel All SL-3 should remain inside the shelter. Strap SL-3 down and secure in accordance with the designated load plan	No	None	SSRI complete

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A2390	5895015344772	SL-3-10446C 123 104462 00 May 2009	No sensitive items contained in this TAMCN. To avoid ESD damage to equipment, attach a grounded wriststrap to wrist and place both hands on a grounded work surface to discharge any residual static electricity. 100% of all SSRI and UURI is to be shipped back to owning unit.	DO NOT POWER WASH INSIDE OF SHELTER. Interior of shelter contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. The exterior of the shelter power washed.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A2525	5895014619786	SL-3-10498B 123 104981 00 Nov 2009	To avoid ESD damage to equipment, attach a grounded wriststrap to wrist and place both hands on a grounded work surface to discharge any residual static electricity. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager. 100% of all SSRI and UURI is to be shipped back to owning unit.	DO NOT POWER WASH INSIDE OF SHELTER. Interior of shelter contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. The exterior of the shelter power washed.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCS C-PMM-122-NET	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A2534	5895014740355	SL-3-10708A	Yes, KG175 Qty 1 and KIV-7HS Qty 2 needs to be WIRED via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy Reynolds.	None	DP5895 PCN 13110834000. This TAMCN is in the process of Disposal.	N/A
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A2535	5895014677469	SL-3-10666A	KIV-7HS Qty 2 needs to be WIRED via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy Reynolds.	None	DP5895 PCN 131589000. This TAMCN is in the process of Disposal. None in theater.	N/A
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A2536	7010090002686	N/A	TAMCN is unclassified		All associated power cords and accessories should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
12	MCS C-PMM-122-NET	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A2538	5895015040650	SL-3-10665A	Yes, KIV-7HS Qty 2 needs to be WIRED via WOLPH through EKMS manager. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code. Handle in accordance with EKMS 1B. POC is Judy Reynolds.	None	DP5895 PCN 13110834000. This TAMCN is in the process of Disposal.	N/A
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010015643767	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010090000382	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010090003753	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.

PG	PMM	MCS C POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010090003756	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010090004287	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010090004288	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7010090004289	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7021090006225	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A2546	7022014779089	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A2548	7010090002543	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A2551	5895014439072	TM-10389A-12&P/1, TM-10389A-30&P/2, ULSS 004996-15 REVISION 2	SSRI - CD81 component is Unclassified Controlled Cryptographic Item (CCI) when unkeyed. Ship via EKMS procedures. Must be transferred from EKMS account to EKMS account. Remaining components are unclassified. TAMCN covers complete set (RT and CD81 and peripherals).	DO NOT POWER WASH. Item contains sensitive electronics, computer, and software which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.	Item has reached its end of service life, and will be replaced by TAMCN A0280, Universal Serial Bus Embedded National Tactical Receiver.	This item is being disposed of. No configuration for fielding required.
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A2555	1220015256305	SL-3-11069B	Removeable Hard Drives classified SECRET should be destroyed in accordance with local Security procedures.	IT Equipment. Do not wash down.	None	This item is being disposed of. No configuration for fielding required.
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A2555	5895015729499	SL-3-11069B	Removeable Hard Drives classified SECRET should be destroyed in accordance with local Security procedures.	IT Equipment. Do not wash down.	These systems will return to the WRMR upon return to MCLC.	
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A2560	7010015244120	SL-3 located in TM. TM 10938B / 10938C OR	Removeable Hard Drives classified SECRET should be destroyed in accordance with local Security procedures.	IT Equipment. Do not wash down.	Complete system contains one PRC-117F radio TAMCN: A2068	
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A2560	7010015716450	SL-3 located in TM. TM 10938B / 10938C OR	Removeable Hard Drives classified SECRET should be destroyed in accordance with local Security procedures.	IT Equipment. Do not wash down.	Complete system contains one PRC-117F radio TAMCN: A2068	
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A2628	7010014653223	SL-3-10648C, FP 10648B, MI 10648C-OI, TM-10618A-13&P/3 TM-10618A-13&P/4	SSRI/UURI listing too large for this format. FSR has current SSRI/UURI listing and is responsible for proper packaging. 100% of SSRI/UURI is to be returned with end item. TAMCN is a sensitive item. Transportation is to be completed IAW local SOP for shipment of sensitive items.	None	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. Conduct all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A2628	7010090004435	SL-3-10648C, FP 10648B, MI 10648C-OI, TM-10618A-13&P/3 TM-10618A-13&P/4	SSRI/UURI listing too large for this format. FSR has current SSRI/UURI listing and is responsible for proper packaging. 100% of SSRI/UURI is to be returned with end item. TAMCN is a sensitive item. Transportation is to be completed IAW local SOP for shipment of sensitive items.	None	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. Conduct all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any
12	MCS C-PMM-125	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A2634	7010090004436	TM 10318A-13&P, FP 10318B, TM10318C-01 SL-3 listed on page B-5 MI 10318B-IN/1 TM-10618A-13&P/3 TM-10618A-13&P/4	SSRI/UURI listing too large for this format. FSR has current SSRI/UURI listing and is responsible for proper packaging. TAMCN is a sensitive item. Transportation is to be completed IAW local SOP for shipment of sensitive items.	None	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. Conduct all repairs/maintenance as required. TAMCN are MARES reportable items, ensure gains and losses are incorporated into unit SORTS reporting.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A2635	5805011255976	N/A	None	None	DP07659. This TAMCN is in the process of disposal.	None
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A2740	6625012577921	SL-3-09076A	None	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B	None	None

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-122-NET	Steven Butt & Ken Hailey	17-Nov; 1030 - 1800	No	A2808	6625012388954	N/A	None	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B	Disposal Plan 09010A is published with disposal actions starting in 3rd quarter FY12.	None
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A3013	5895090004022	SL-3-11092A	The TAMCN is not classified as sensitive unless the laptop has been used to store classified data. If the hard drive is marked classified, the using unit should remove the hard drive and retain it. A new hard drive can be obtained by CLS support after return from OEF. There are no specific procedures for disassociating the hard drive from the SECREP contained within the TAMCN.	The Pelican case can be washed; all equipment stored within the Pelican cases are electronic equipment and should not be subjected to water washdown.	Recommend no local nationals transport this gear as it contains equipment that is considered highly pilferable. (i.e COTS ITE)	same as configuration used OCONUS
12	MCS C-PMM-122-ADM	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A3200	2330002154211	N/A	None	None	SI10119A There is no replacement TAMCN. Obsolete and no requirement to stay in inventory. TESMS NSN: 2330011675116	None
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A3232	5895014350571	SL-3-10432A	No, TAMCN itself is not classified? Yes, SSRI or UURI items are classified sensitive. CRYPTO must have a NAVMC 1018 tag with PEI serial number, PEI shipped to, and PEI condition code. Handle in accordance with EKMS 1B & 5A.	Do not pressure wash. Only use fresh non potable water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. Handle in accordance with EKMS 1B & 5A.	Do not separate weapon system from HMMWV. *This item has a Depot strategy and should be sent to Tobyhanna Army Depot for reset; contact PO prior to issue to coordinate upgrade schedule. Always ship MILAIR, due to detailed handling requirements to prevent antenna damage.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	PMA263	Dave Schrumm	17-Nov; 0900 - 1030	No	A3252	1550015303912	SL-3-11-15B PCN 123 110151 00	All hard drives will remain with the Equipment for repair/return. If the hard drive contains classified information it will remain maintained by the owning unit. be stored IAW procedures contain local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hardware will be coordinated between the owning unit and the NAVAIRSYSCOM Project Office.	DO NOT POWER WASH. Use damp rags and compressed air to clean this TAMCN and its equipment.	PMA-263 has the cog for this item. POC is Capt. Steven M. Stepanic PMA-263 Raven B and WASP Lead at (301)757-1796. Please direct inquiries about this item to PMA-263.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
11	PMA263	Dave Schrumm	17-Nov; 0900 - 1030	No	A3252	1550015389256	SL-3-11-15B PCN 123 110151 00	All hard drives will remain with the Equipment for repair/return. If the hard drive contains classified information it will remain maintained by the owning unit. be stored IAW procedures contain local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hardware will be coordinated between the owning unit and the NAVAIRSYSCOM Project Office.	DO NOT POWER WASH. Use damp rags and compressed air to clean this TAMCN and its equipment.	PMA-263 has the cog for this item. POC is Capt. Steven M. Stepanic PMA-263 Raven B and WASP Lead at (301)757-1796. Please direct inquiries about this item to PMA-263.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.

PG	PMM	MCSC POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	PMA263	Dave Schrumm	17-Nov; 0900 - 1030	No	A3252	1550015495291	SL-3-11-15B PCN 123 110151 00	All hard drives will remain with the Equipment for repair/return. If the hard drive contains classified information it will remain maintained by the owning unit. be stored IAW procedures contain local Standard Operating Procedures (SOP). Unserviceable Classified hard drives will be disposed of locally in accordance with Marine Corps Orders and local SOP's. Replacement of defective hardware will be coordinated between the owning unit and the NAVAIRSYSCOM Project Office.	DO NOT POWER WASH. Use damp rags and compressed air to clean this TAMCN and its equipment.	PMA-263 has the cog for this item. POC is Capt. Steven M. Stepanic PMA-263 Raven B and WASP Lead at (301)757-1796. Please direct inquiries about this item to PMA-263.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCSC-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A3255	6350013437134	SL-3-09632A	None of this equipment is classified as sensitive.	This is electronic gear and should not be agriculturally washed.	No	same as configuration used OCONUS
11	MCSC-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A3270	5895015800283	SL-3-10576D 123 105763 00 Dec 2009	TAMCN A8023 Data Transfer Device and Simple Key Loader (SKL) need to be shipped IAW SOP and guidance from the EKMS manager. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager. Receiver transmitters associated with TAMCN A0126 and A0266 should be prepared for transport IAW SOP and EKMS manager's guidance. 100% of all SSRI and UURI is to be shipped back to owning unit.	DO NOT POWER WASH INSIDE OF SHELTER. Interior of shelter contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. The exterior of the shelter plus the HMMWV may be power washed.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow headaches.	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
	MCSC-PMM-203			No	A5008	7010015440346	N/A	NO classified sensitive items are included.	Computer Equipment - DO NOT WASH DOWN.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7001	6650015107502	SL-3-10758A	NO classified sensitive items are included. - SL-3 components (SSRI) should be shipped with system.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7002	6625015306573	SL-3-11230A	NO classified sensitive items are included.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7004	6650015309446	SL-3-11397A	NO classified sensitive items are included.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7005	6625014651844	SL-3-10775A	NO classified sensitive items are included.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7005	6625015229603	SL-3-11354A	NO classified sensitive items are included.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7009	6625015406124	SL-3-11455A	NO classified sensitive items are included.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7010	6625012055224	DP 09905A	NO classified sensitive items are included.	N/A		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7021	6625012713012	POP 09163A	NO classified sensitive items are included.	N/A		

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7021	6625013992298	SL-3-10607A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7021	6625015309444	SL-3-11307A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7035	5895012810072	SL-3 components (SSRI) is a POWER CORD and he counter only (Part Number 8120-1348) and should be shipped with system. SL-3 components (SSRI) is a POWER CORD and he counter only (Part Number 8120-1348) and should be shipped with system.	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7035	6625013584903	SL 3-09152B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7036	6625014164444	SL-3-10480A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7036	6625015498266	SL-3-10480B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7040	6625015051143	SL-3-11089A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7046	6625013959570	SL-3-10170A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7046	6625014252550	SL-3-10758A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7046	6625014955275	SL-3-10758B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7051	6625014066941	SL-3-10236A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7051	6625015311947	SL-3-10236B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7052	6625013675551	SL-3-09792A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7053	6625013815741	DP 10225A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7055	6625012175631	DP09916A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7055	6625014439916	DP 09916B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7055	6625015134644	SL-3-09916C	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7055	6625015682691	SL-3-11823A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7057	6625013778030	POP - ULSS 007391-15	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7057	6625014943112	SL-3-10096B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7059	6625013776166	SL-3-10069A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7060	6625014518727	POP - SI 10479A-OI/2	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7060	6625015196497	SL-3-11277A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7061	6625012754766	POP - ULSS 002390-15	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7061	6625014735174	POP ULSS 002390-15	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7061	6625014940438	SL-3-10771B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7072	6625013092827	POP - SI 09419A-OI	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7072	6625014328368	SL-3-09419B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7072	6625014360419	Not A Marine Corp Asset	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7080	6625012396715	POP 10049A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7080	6625015380285	SL-3-11290A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7081	6625013401781	POP 09608A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7081	6625014627492	POP 09608D	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7081	6625015358961	SL-3-11269A	NO classified sensitive items are included.	N/A		

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7082	6625013092825	SL-3-09311A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7083	6625015229579	SL-3-10986B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7084	6625014561561	POP 10405B	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7084	6625014848826	SL-3-10812A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7084	6625015378768	SL-3-11366A	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7086	6625013884989	POP - SI 10156A-OI/1	NO classified sensitive items are included.	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7086	6625015253080	SL-3-11270A	NO classified sensitive items are included.	N/A		
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7100	6720015007726	N/A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7102	5836015281482	N/A	Recommend removal of this - PAE legacy equipment replaced by A7203	Recommend removal of this - PAE legacy equipment replaced by A7203	Recommend removal of this - PAE legacy equipment replaced by A7203	Recommend removal of this - PAE legacy equipment replaced by A7203
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7103	6720015150429	N/A				
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7104	5836015425653	SL-3-11310A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7105	5836015003247	SL-3-10892B	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7105	5836015458734	SL-3-10892B	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7111	5855015429059	SL-3-11314A	None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7112	7010015464691		None of this equipment is classified as sensitive	This is electronic gear and should not be agriculturally washed.	This equipment should not be transported by Local nationals due to the highly pilferable nature of this equipment.	Same configuration as OCONUS
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A7200	5836015430022	N/A	NA	NA	No	NA
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	A7201	6740015430653	N/A	NA	NA	No	NA
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A7202	5836015430308	N/A	NA	NA	No	NA
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A7203	6720015430652	N/A	NA	NA	No	NA
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A7204	5895015707690	N/A	NA	NA	No	NA
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A7205	5855015579470	N/A	NA	NA	No	NA
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	Yes	A7206	5895015702488	N/A	NA	NA	No	NA
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7420	4940014904064	SL-3-10811A	N/A	Nothing beyond standard procedures.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7501	6625014849160	POP 10793A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7501	6625015347363	SL-3-10793D	N/A	N/A		

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7501	6625015347365	SL-3-10793C	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7503	6625015500389	SL-3-11510A				
16	MCS C-PMM-164	Michael Roberts	18-Nov; 0915 - 1415	No	A7504	5999015644048	SL-3-11595A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7507	6625015588041	SL-3-11504A				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7508	6625015453668	SL-3-11708A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	Yes	A7509	6625015601265	SL-3-11635B	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7512	6625015136360	DP 10989A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7513	6625015244047	SL-3-11070A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7517	6625015634671	SL-3-11583A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7519	6625015659818	SL-3-11618A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7522	6625015754978	SL-3-11765A				
12	MCS C-PMM-122-SAT	Roger Wood & Rose Boudreau	17-Nov; 1030 - 1800	No	A7545	5895090002545	SL-3-10939A	N/A	Do not pressure wash. Only use fresh non potable water, do not use saltwater.	Bring back as complete kit TAMCN associated with A0806 & A0807 LMST (V)1 & (V)2	N/A
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7550	6625015154038	SL-3-11018A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7596	6625015659249	SL-3-11635A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7596	6625015685523	SL-3-11635B	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7597	6625015678650	SL-3-11635B	N/A	N/A		
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A7700	6130013412073	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A7705	6130014528403	SL-3: SL-3-10911A		NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A7705	6130014754999	SL-3: SL-3-10911A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A7706	6130015319927	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	A7706	6130219116149	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7900	5180012241290	DP 09015A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7900	5180012441290	DP 09015A				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7902	4940015540475	DP 11477A	N/A	N/A		
11	MCS C-PMM-113	Dave Schrumm	17-Nov; 0900 - 1030	No	A7905	5895014527551	SL-3-10484A 123 104840 00 May 2000	TAMCN is a tool kit. Refer to SL-3 for a list of SSRI/UURI. 100% of all SSRI and UURI is to be shipped back to owning unit.	DO NOT POWER WASH ELECTRONIC ITEMS OR TOOLS. Compressed air, vacuums, and damp rags should be used to clean the tools and tool box. Hand tools (sockets, screwdrivers, etc.) should be lightly coated with oil. Electronic tools need to remain dry.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	Yes	A7906	5180015416262	SL-3-11302A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7910	5180014763023	SL-3-10785A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7910	5180015167227	SL-3-10785B	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7920	6080015208198	SL-3-11088A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7942	5180015247623	SL-3-11058A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7955	5895013229872	SL-3-09458A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7955	5895015429039	SL-3-09458B	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	A7955	5895015662941	SL-3-09458C	N/A	N/A		

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
11	MCS C-PMM-111	Richard Frank	17-Nov; 0900 - 1030	No	A7965	6080014624026	No Publications or documentation could be found. TAMCN should be transferred back to PG-16, TMDE	TAMCN is a tool kit. Refer to SL-3 for a list of SSRI/UURI. 100% of all SSRI and UURI is to be shipped back to owning unit.	DO NOT POWER WASH ELECTRONIC ITEMS OR TOOLS. Compressed air, vacuums, and damp rags should be used to clean the tools and tool box. Hand tools (sockets, screwdrivers, etc.) should be lightly coated with oil. Electronic tools need to remain dry.	Upon receiving item from theater, owning unit needs to complete a detailed SL-3 inventory and a detailed maintenance assessment. The inventory and assessment will drive the amount of organic supply support needed (i.e. replacing SL-3), organic maintenance (i.e. radio maintenance, cable maintenance), and depot maintenance (i.e. IROAN). The detailed assessment will assist in preparing the depot for incoming work and alleviate overflow	After all equipment has been returned from maintenance or supply system, the Code A asset - SL-3 complete with SSRI and UURI - will be placed back into full service at the owning unit. Code A, SL-3 complete with UURI/SSRI is to be interpreted as the same condition as originally fielded plus any software/hardware upgrades/modifications.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8008	5810010828412	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column "v".	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	NAVMC 1018 Tag annotation requirements for the OEF redeployment of CCI. 1. If CCI is "stand alone" or not associated to a PEI TAMCN SIDE A -Main Information Date ERO# Owning Unit EKMS Account # Condition Code PQDR # Warranty status (If applicable) Configuration Management (i.e. Software version, firmware version, strap setting/cut sheet and battery information) Modifications work. (Modifications are directed and authorized by NSA for application by NSA approved facilities to be performed by trained Depot CCI technicians). Inspectors name and grade 2. If CCI is SECREP or component SIDE A -Main Information Date ERO# Owning Unit Nomen of end item ID # of end item	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8010	5810014596438	N/A	TAMCN is not classified Sensitive. This item has a CCI token that is hard keyed to user requirements. This token is neither SSRI or UURI, however it has the one capability as required with this TAMCN. Disassociation of the token to the STE is to be done at the associated STE. If this is not completed correctly the token cannot be reassocated to another STE and will require zeroization. STE's can be bulk shipped as with any other non-controlled IT or telecommunications equipment. The token is shipped per the EKMS 1B in accordance with the classification of the resident key.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8010	5810014596441	N/A	TAMCN is not classified Sensitive. This item has a CCI token that is hard keyed to user requirements. This token is neither SSRI or UURI, however it has the one capability as required with this TAMCN. Disassociation of the token to the STE is to be done at the associated STE. If this is not completed correctly the token cannot be reassocated to another STE and will require zeroization. STE's can be bulk shipped as with any other non-controlled IT or telecommunications equipment. The token is shipped per the EKMS 1B in accordance with the classification of the resident key.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8018	5810000613388	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8018	5810012737819	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8019	5810000613386	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8023	5810013431194	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8023	5810013841996	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8023	5810013887634	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8023	5810013931973	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8023	5810015173587	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-ADM	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8024	5810010269620	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8025	5810010269618	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.

PG	PMM	MCS POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS-PM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8027	5810010269621	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-ADM	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8028	5810010269622	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8031	5810004343644	N/A	TAMCN is not classified Sensitive. Crypto must have a NAVMC 1018 Tag with PEI Serial #, PEI Unit Shipped To, PEI Condition Code	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8032	5810004490154	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8036	5810013687752	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8038	5810010168052	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8038	5810013513000	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8047	5810013910187	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8047	8340015120240	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS-PM-122-CMS	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8050	6140010488167	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-122-ADM	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8067	5810011608398	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8072	5810012486018	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8081	5810012240202	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8082	5810011463260	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Roger Wood & Steven Butt	17-Nov; 1030 - 1800	No	A8082	5810012506618	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8084	5810014146656	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8084	5810014304225	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8084	5810014318264	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8084	5810014876582	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8084	5810015302811	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8085	5810014497179	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8085	5810014925165	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8085	5810014989537	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8088	5810014861987	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8088	5810015279296	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8088	5810015474520	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8088	5810014630133	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8089	5810012831394	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.	Owning unit request disposition instructions from NCMS.	If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8091	5810015246615	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 9.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8098	5810013517228	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8098	5810010060622	N/A	TAMCN is not classified Sensitive. Handle in accordance with EKMS 1B. TAMCN should follow PEI disposition Classified shipping instructions: DCO Courier, Hand carried, USPS Mail - Registered Mail Sensitive. Please see amplifying comments in column 10.	Do not pressure wash. Only use fresh water, do not use saltwater. The corrosion from the saltwater will render the weapon system non mission capable. At a maximum a low pressure air blast (Not To Exceed (NTE) 20psi) and damp cloth bath are appropriate. Handle in accordance with EKMS 1B.		If TAMCN is associated with PEI or radar systems, handle and ship concurrent with associated PEI.
12	MCS C-PMM-122-CMS	Ken Hailey	17-Nov; 1030 - 1800	No	A8100	5895014294556	SL-3-10267A	All radios systems are controlled Items. All radios systems have imbedded CCI. Recommendation that CCI should be shipped in accordance with Electronic Keys Management System (EKMS-1).	Recommendation: Do Not Power Wash. Use damp rags and compressed air to clean this TAMCN and associated SL-3 equipment.	Recommend that the owning unit dispose of the equipment IAW local DRMO policy: POC Robert Jackson, 229-639-5066 for disposal Plan.	This item is being disposed of. No configuration for fielding required.
Not Assigned	MCS C-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	A8300	7010090000283					
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	Yes	A9001	7010015138459	N/A	N/A	Yes, it is a computer system - HIGHLY SENSITIVE TO WATER INTRUSION.		
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A9002	5865015335325	N/A	N/A	N/A		
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	Yes	A9003	5865015335336	N/A	N/A	N/A		
11	MCS C-PMM-114	Richard Frank	17-Nov; 0900 - 1030	No	A9004	7010015154227	SL-3-11238B	N/A	IT Equipment. Do not wash down.	NONE	
10	MCS C-PMM-103	Mike McAuliffe - Dial In	17-Nov; 0800 - 0900	No	A9010	7010015431630	N/A	N/A	None	None	None
10	MCS C-PMM-103	Chris Hegland - Dial In	17-Nov; 0800 - 0900	No	A9011	7050015444379	N/A	N/A	None	None	None
10	MCS C-PMM-103	Kathy Embry	17-Nov; 0800 - 0900	No	A9013	7021015504906	N/A	This TAMCN itself is not classified sensitive. However, the hard drive may have medical patient data resident that will need to be backed up and provided to the retrograding medical treatment facility commander before degaussing of hard drives. The data back-up and degaussing is accomplished in-country by the TMIP-USMC Field Service Representative according to the TMIP-USMC Retrograde Plan. The TMIP-USMC FSR will then ship the TMIP-USMC equipment to SPAWARSYSCEN	IT Assets are not required to be washed down the TMIP-USMC FSR will accomplish this task.	None noted	
10	MCS C-PMM-103	Kathy Embry	17-Nov; 0800 - 0900	No	A9014	7022015508555	N/A	This TAMCN itself is not classified sensitive. However, the hard drive may have medical patient data resident that will need to be backed up and provided to the retrograding medical treatment facility commander before degaussing of hard drives. The data back-up and degaussing is accomplished in-country by the TMIP-USMC Field Service Representative according to the TMIP-USMC Retrograde Plan. The TMIP-USMC FSR will then ship the TMIP-USMC equipment to SPAWARSYSCEN	IT Assets are not required to be washed down the TMIP-USMC FSR will accomplish this task.	None noted	
10	MCS C-PMM-103	Kathy Embry	17-Nov; 0800 - 0900	No	A9015	7022015508375	N/A	This TAMCN itself is not classified sensitive. However, the hard drive may have medical patient data resident that will need to be backed up and provided to the retrograding medical treatment facility commander before degaussing of hard drives. The data back-up and degaussing is accomplished in-country by the TMIP-USMC Field Service Representative according to the TMIP-USMC Retrograde Plan. The TMIP-USMC FSR will then ship the TMIP-USMC equipment to SPAWARSYSCEN	IT Assets are not required to be washed down the TMIP-USMC FSR will accomplish this task.	None noted	
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9020	7021090006232	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII	COTS asset. Configuration is aset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9020	7021090006470	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII	COTS asset. Configuration is aset at time of purchase.
10	MCS C-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9023	7010090006435	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII	COTS asset. Configuration is aset at time of purchase.

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
GCS	MCS-GCS-MC	Maj Todd O'Brien	18-Nov; 0900 - 0915	Yes	A9068	5895015703725	It is a laptop and has no associated SL-3 gear.	Most BCS3 machines that are forward are used on the SIPRnet. Harddrives should be removed from the laptop and disposed of as per local security office guidelines. Following hard drive removal, the laptop is not sensitive and can be shipped normally.	There are no specific instructions as to agricultural washdown.	None.	N/A
GCS	MCS-GCS-MC	Maj Todd O'Brien	18-Nov; 0900 - 0915	Yes	A9068	5895015729492	It is a laptop and has no associated SL-3 gear.	Most BCS3 machines that are forward are used on the SIPRnet. Harddrives should be removed from the laptop and disposed of as per local security office guidelines. Following hard drive removal, the laptop is not sensitive and can be shipped normally.	There are no specific instructions as to agricultural washdown.	None.	N/A
GCS	MCS-GCS-MC	Maj Todd O'Brien	18-Nov; 0900 - 0915	Yes	A9068	7010015329207	It is a laptop and has no associated SL-3 gear.	Most BCS3 machines that are forward are used on the SIPRnet. Harddrives should be removed from the laptop and disposed of as per local security office guidelines. Following hard drive removal, the laptop is not sensitive and can be shipped normally.	There are no specific instructions as to agricultural washdown.	None.	N/A
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9071	7010090006216	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
11	MCS-PMM-114	Richard Frank	17-Nov; 0900 - 1030	Yes	A9089	7010015542356	N/A				
11	MCS-PMM-114	Richard Frank	17-Nov; 0900 - 1030	Yes	A9089	7010015690604	N/A				
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010014649363	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090000294	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090000346	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090002538	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090002539	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090002540	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090004272	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090004448	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7010090006210	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9100	7022014779043	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9200	7010090000350	N/A	This TAMCN is obsolete and should be DRMOD or disposed of in theater.	This TAMCN is obsolete and should be DRMOD or disposed of in theater.	This TAMCN is obsolete and should be DRMOD or disposed of in theater.	This TAMCN is obsolete and should be DRMOD or disposed of in theater.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9300	7010014649346	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCS-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9300	7010090000349	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.

PG	PMM	MCSC POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
10	MCSC-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9300	7010090006211	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCSC-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9300	7022014778695	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCSC-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	Yes	A9400	7010090000347	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
10	MCSC-PMM-101	Kathy Embry	17-Nov; 0800 - 0900	No	A9500	7035014649366	N/A	TAMCN is unclassified	IT Equipment. Do not wash down.	All associated power cords and power supplies should be shipped with PEI. HDD should be reformatted IAW local SOP to ensure there is no loss of classified material or PII.	COTS asset. Configuration is asset at time of purchase.
		Stephen Magee	18-Nov; 1415 - 1500	No	B0000	#N/A		N/A	N/A	N/A	N/A
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0003	4120015261588	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0003	4120015810399	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0006	4120004443921	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0006	4120009264137	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0006	4120010726388	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0006	4120011608886	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0006	4120011755902	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0006	4120012446385	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0008	4120015261060	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0008	4120015410646	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	THIS NSN IS NOT A B0008 FIELD BY MARCORSYSCOM!	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0008	4120015812260	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0010	4120015261120	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0010	4120015647844	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0010	4120015811227	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SI-3 complete"	NA	None.	NA

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0010	same listed twice	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0011	4120003237780	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0011	4120011508112	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	Yes	B0013	4120013590083	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete"	NA	None.	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0014	4120015262397	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0014	4120015811276	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
PM MRAP	MCSC-PMM-154	Mark Billow - Dial In	14-Nov; 0900 - 1000	Yes	B0015	2330015640135	Draft SL-3 at Albany for review and publishing	This TAMCN is not classified as sensitive. There is no SSRI or UURI items that are classified sensitive. This equipment in its entirety should be shipped to MCLB Albany.	Power washing may be completed on the exterior (outside) only of this item. Care should be taken around wiring to prevent damage. DO NOT POWER WASH INSIDE OF SHELTER; interior contains sensitive electronics which water can damage. Use compressed air.	Upon MCLB Albany Receiving equipment from theater, PM-CIED should be contacted so a complete inventory assessment can be performed to ascertain the equipments reliability status. POC: Mr. Mark J. Billow, PM-CIED, (703) 462-4961.	This equipment is not a program of record and is not owned by any using unit. Therefore no configuration for fielding is required.
PM MRAP	MCSC-PMM-154	Mark Billow - Dial In	14-Nov; 0900 - 1000	Yes	B0015	6665015314806	N/A	N/A	N/A	Systems transferred to Army I/A/W ZBV Disposal Plan dated 17 Sep 09 and MARCENT message DTG: 090720Z	N/A
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0017	5280015714894	SL-3-11703A PCN 12311703000	NOT CLASSIFIED	NONE	NONE	None
15	MCSC-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0018	2330015569648	SL-3: SL-3-11490A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not to overspray onto electrical components. For the ECU: The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to	SL-3: SL-3-11490A	NA
	MCSC - PMM-152	Mike Callahan		Yes	B0023	6665015315570		N/A	N/A	N/A	N/A
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0024	3825014970690	TM 5-3800-205-10-2 Table 1 Chapter 6	Not Classified	TANK MUST BE FLUSHED	NONE	NA
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0025	3710015357449	TM 11241A-01 Table 1 Chapter 6	Not Classified	TANK MUST BE FLUSHED	NONE	NA
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0026	3710015349817	TM11234A-01 Table 1 Chapter 6	Not Classified	TANK MUST BE FLUSHED	NONE	NA

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0027	6110015321794	SL-3: SL-3-6110	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Power distribution boxes (MEPDIS-R) should have the external air vents, including the vents underneath the unit taped closed before any water is directed at the unit. Also all connector covers should be tightly closed. MEPDIS-R can be cleaned with high pressure water if the connector covers are closed and the vents are taped shut with no damaging effects to the unit.	SL-3: SL-3-6110	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0028	6110015321821	SL-3: SL-3-6110	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Power distribution boxes (MEPDIS-R) should have the external air vents, including the vents underneath the unit taped closed before any water is directed at the unit. Also all connector covers should be tightly closed. MEPDIS-R can be cleaned with high pressure water if the connector covers are closed and the vents are taped shut with no damaging effects to the unit.	SL-3: SL-3-6110	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0029	6110015321764	SL-3: SL-3-6110	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Power distribution boxes (MEPDIS-R) should have the external air vents, including the vents underneath the unit taped closed before any water is directed at the unit. Also all connector covers should be tightly closed. MEPDIS-R can be cleaned with high pressure water if the connector covers are closed and the vents are taped shut with no damaging effects to the unit.	SL-3: SL-3-6110	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0030	6110015321809	SL-3: SL-3-6110	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Power distribution boxes (MEPDIS-R) should have the external air vents, including the vents underneath the unit taped closed before any water is directed at the unit. Also all connector covers should be tightly closed. MEPDIS-R can be cleaned with high pressure water if the connector covers are closed and the vents are taped shut with no damaging effects to the unit.	SL-3: SL-3-6110	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0031	6110015321835	SL-3: SL-3-6110	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Power distribution boxes (MEPDIS-R) should have the external air vents, including the vents underneath the unit taped closed before any water is directed at the unit. Also all connector covers should be tightly closed. MEPDIS-R can be cleaned with high pressure water if the connector covers are closed and the vents are taped shut with no damaging effects to the unit.	SL-3: SL-3-6110	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0032	6110015321776	SL-3: SL-3-6110	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Power distribution boxes (MEPDIS-R) should have the external air vents, including the vents underneath the unit taped closed before any water is directed at the unit. Also all connector covers should be tightly closed. MEPDIS-R can be cleaned with high pressure water if the connector covers are closed and the vents are taped shut with no damaging effects to the unit.	SL-3: SL-3-6110	NA
PM MRAP	MCS C-PMM-154	Mark Billow - Dial In	14-Nov; 0900 - 1000	No	B0033	2320015322159	N/A			USMC is divesting of this NSN.	

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0034	2355015602318	TAMCN being archived and equipment being reported under B0092, B0093 or B0094 TAMCNs.	N/A	NO	TAMCN being archived and equipment being reported under B0092, B0093 or B0094 TAMCNs.	NONE
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	B0035	2355015316425	SL-3 11217/11606A	UURI items that are sensitive will be disassociated by the WIR instructions; directing all UURI to be kept and disposed of by the owning unit. Excess UURI should be vetted by MARCENT and JPO Log Forward to fill short falls in EDLs.	Remove all C4I asset and disassociate prior to wash down. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.	Both Variants of CAT III Buffalos are returning to MCLB Albany for Reset prior to fielding according to R2C and enduring requirements.	SSRI to be fielded in CONUS upon completion of RESET and fielding R2C identified units.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	B0035	2355015811171	SL-3 -11606B	UURI items that are sensitive will be disassociated by the WIR instructions; directing all UURI to be kept and disposed of by the owning unit. Excess UURI should be vetted by MARCENT and JPO Log Forward to fill short falls in EDLs.	Remove all C4I asset and disassociate prior to wash down. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.	Both Variants of CAT III Buffalos are returning to MCLB Albany for Reset prior to fielding according to R2C and enduring requirements.	SSRI to be fielded in CONUS upon completion of RESET and fielding R2C identified units.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0036	4930015339826	TM 11219A/11220A-OI, WP 25 & 26	NA	Liners cannot be returned to CONUS if placed in-service. All hoses and nozzles must be certified gas free.	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0037	4930015339830	TM 11219A/11220A-OI, WP 25 & 26	Not Classified	Liners cannot be returned to CONUS if placed in-service. All hoses and nozzles must be certified gas free.	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0038	3810015384030	TM 11262A-OI-P Workpackage / Page 00-553	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0038	3810015793981	TM 11262A-OI-P Workpackage / Page 00-553	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0039	3895015390585	TM 11275A-OI/1 Volume 1 Table 1 Chapter 2 Containers 1-3	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0040	3805015393925	No SL 3 Components- associated tools are part of B0076	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0040	3805015500883	No SL 3 Components- associated tools are part of B0076	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0040	3805015696091	No SL 3 Components- associated tools are part of B0076	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0040	3805015804542	No SL 3 Components- associated tools are part of B0076	Not Classified	NA	NA	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0044	2590992389283	TM 10984A-OI/2-2 Pg 0002 00-155 thru 0002 00-553	Not Classified	NONE	NONE	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0048	1385015936219	No SL/3	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	N/A	None	28 systems already fielded CONUS for HST. Systems will be replaced with R2C Robot in FY13.
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0049		NA; NO NSN LISTED.	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	A pressure washer can be used on the interior and exterior of the box, excluding the Refrigeration Unit (RU). The RU needs to be cleaned using compressed air and coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-11574A. MARCORSYSCOM has not shipped ANY of this TAMCN / NSN to OEF, so none of these are in OEF to our knowledge. Commercial boxes may look similar, but are white in color and do not have the safety features of the USMC LFRS.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0049		SL-3: SL-3-11574A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	A pressure washer can be used on the interior and exterior of the box, excluding the Refrigeration Unit (RU). The RU needs to be cleaned using compressed air and coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-11574A. MARCORSYSCOM has not shipped ANY of this TAMCN / NSN to OEF, so none of these are in OEF to our knowledge. Commercial boxes may look similar, but are white in color and do not have the safety features of the USMC LFRS.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0049	4130015629914	SL-3: SL-3-11574A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	A pressure washer can be used on the interior and exterior of the box, excluding the Refrigeration Unit (RU). The RU needs to be cleaned using compressed air and coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-11574A. MARCORSYSCOM has not shipped ANY of this TAMCN / NSN to OEF, so none of these are in OEF to our knowledge. Commercial boxes may look similar, but are white in color and do not have the safety features of the USMC LFRS.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0049	4130015629914	SL-3: SL-3-11574A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	A pressure washer can be used on the interior and exterior of the box, excluding the Refrigeration Unit (RU). The RU needs to be cleaned using compressed air and coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-11574A. MARCORSYSCOM has not shipped ANY of this TAMCN / NSN to OEF, so none of these are in OEF to our knowledge. Commercial boxes may look similar, but are white in color and do not have the safety features of the USMC LFRS.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0049	4130015629914	SL-3: SL-3-11574A	NA	NA	None have been shipped to OEF!!!	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0055	4510011636775	SL-3-10006A	Not classified	All water lines need to be rinsed and purged prior to shipping to CONUS.	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0058	2590015439655	N/A	Not Classified	None	None	None

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0058	2590015447173	N/A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0058	2590015456776	N/A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0058	2590015536517	N/A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0058	2590015794990	N/A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0060	2320015585671	N/A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0060	2320015895117	N/A	Not Classified	None	None	None
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0061	4120015585664	SL-3: SL-3-11502A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	All tools need to be wiped down and the exterior of the cases can be cleaned with low pressure washer.	SL-3: SL-3-11502A	NA
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B0062	5180015500145	SL-3-11509A	N/A	N/A		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0063	3805015497814	N/A	Not Classified	N/A	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0065	3815015503454	No SL-3 published	Not Classified	N/A	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0066	3510015498384	TM 11413A-OI/1, PAGES 0099 002-004	Not Classified	All water lines need to be rinsed and purged prior to shipping to CONUS.	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0067	1040015503421	TM 11512A-OI/2 Chapter 5 Table 1	Not Classified	N/A	N/A	N/A
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B0069	4240002739668	Not a Marine Corps Asset	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B0069	5180015508373	SL-3-11418A	N/A	N/A		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0071	4610015728283	TM 11720A-OI, PAGES WP 0049	Not Classified	All water lines need to be rinsed and purged prior to shipping to CONUS.	N/A	N/A
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0074	4120015525223	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0074	4120015812650	SL-3: SL-3-4120	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should be cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-4120	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0075	4130015657655	SL-3: SL-3-11609A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	A pressure washer can be used on the interior and exterior of the box, excluding the Refrigeration Unit (RU). The RU needs to be cleaned using compressed air and coils need to be cleaned from the inside out in order to properly clean them out.	SL-3: SL-3-11609A	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0076	3805015534073	No S/L-3	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0077	6115012747387	Contact G-BOSS Program Office since the generator is a component of their system.	Contact G-BOSS Program Office since the generator is a component of their system.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	None.	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0078	3805015660558	TM11621A-OR Work Package 0031 Table 1	No	No	None	No Change
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0078	3805015982715	TM11621A-OR Work Package 0031 Table 1	No	No	None	No Change
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0079	3830015626715	N/A	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0081	3830015626695	N/A	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0085	3450015700732	N/A	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0086	2590991338188	N/A	NOT CLASSIFIED	NONE	NONE	None

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0089	5420015805748	URGENT UUNS No SL-3 or TM exists for this equipment.	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0090	3940002023601	N/A	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0091	2910015879196	N/A. No reset plan. DRMO in OEF.	Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0092	2330015294229	TM 11772A-OR/1 Page 0053-1 thru 17	N/A	NO	Used by B0093	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0093	2355015602306	TM 11772A-OR/1 Page 0053-1 thru 17	N/A	NO	NONE	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0094	2541015602332	TM 11772A-OR/1 Page 0053-1 thru 17	N/A	NO	Used by B0093	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0096	2590015890393	N/A	N/A	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0100	3940002023614	N/A	N/A	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0102	6665123710357	N/A	N/A	NO	FSR's are in place to perform all maintenance	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0105	6665151952879	N/A	no	no	no	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0120	5420001723519	SL-3-08675A	N/A	NO	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0152	5420001723520	SL-3-08676A	N/A	NO	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0160	2350015117783	TM 10984A-OI/2-2 Pg 0002 00-35 thru 0002 00-97	TAMCN is not sensitive. Associated radios and cameras are classified sensitive and should be packaged and shipped separately.	Remove cameras before washdown.	NONE	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0171	3815015515938	N/A	Not Classified	None	None	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0176	3815012919223	N/A	Not Classified	None	None	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0215	3830014828567	N/A	Not Classified	None	None	N/A
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	B0281	6720015938038	N/A	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	B0281	6720090004310	N/A	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0338 (instructions for the "A" TAMCN is also included in this R2 Playbook).
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	B0282	6720015937979	N/A	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	B0282	6720090004311	N/A	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0339 (instructions for the "A" TAMCN is also included in this R2 Playbook).
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	B0283	5836015922160	N/A	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	B0283	5836090004313	N/A	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).	This TAMCN is obsolete and is now reflected as A0340 (instructions for the "A" TAMCN is also included in this R2 Playbook).
13	MCS C-PMM-131	Stephen Magee	14-Nov; 1000 - 1500	No	B0360	4310012501034		Not Classified	N/A	N/A	N/A
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0391	3930012694938	N/A		Replaced by the B0392	Replaced by the B0392	Replaced by the B0392
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0392	3930015227364	TM10-3930-675-10-1 Chapter 5 Table 2	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0395	3820015427652	SL-3-08917A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0395	4310014988886	SL-3-08917A	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0446	3810011650646	TM5-3810-305-10 Chapter 1 Section X	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0446	3810015169718	TM5-3810-305-10 Chapter 1 Section X	Not Classified	None	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B0446	3810015789682	TM5-3810-305-10 Chapter 1 Section X	Not Classified	None	None	None
Not Assigned	MCS C-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	B0465	4230014705826		Not Classified	N/A	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0471	1375000473750	SL-3-00482B	N/A	NO	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0471	1375002124589	OBSELETE REPLACED BY NSN 1375000473750	N/A	NO	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0472	1375000473751	SL-3-01518A	N/A	NO	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0475	6665001447655	N/A	N/A	NO	None	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0475	6665219061023	SL-3-03701E	N/A	NO	None	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0476	6665015047769	SL-3-11001B	N/A	NO	None	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0476	6665015274643	SL-3-11001B	N/A	NO	None	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0570	8110009652313	TM-04486B-15, PAGE 1-3	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0571	8110011220015	TM 10-8110-202-138P, PAGES D1-D7	Not Classified	N/A	If water has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0572	5430014795116	SL-3-10761A	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0573	2910015391071	SL-3-10803B	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0573	5430014850103	SL-3-10803B	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0573	5430014858340	DRMO-NOT MARINE CORPS	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0573	5430015427938	DRMO-NOT MARINE CORPS	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0574	5430010586293	SL-3-06999C	Not Classified	N/A	If fuel has been introduced to the system it cannot be returned to CONUS.	NONE
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0579	6150013062943	SL-3: SL-3-07500C	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Load banks require special consideration. The internals of a load bank should never be cleaned with running water. Damp cloths can be used to wipe out any residue vacuums won't remove. Water can be used to clean the exterior of a load bank as long as all doors are tightly closed and high pressure water is not directed into any seam or opening on the load bank.	SL-3: SL-3-07500C	NA
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0579	6150015571304	SL-3: SL-3-07500C	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	Load banks require special consideration. The internals of a load bank should never be cleaned with running water. Damp cloths can be used to wipe out any residue vacuums won't remove. Water can be used to clean the exterior of a load bank as long as all doors are tightly closed and high pressure water is not directed into any seam or opening on the load bank.	SL-3: SL-3-07500C	NA
Not Assigned	MCS-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	B0585	6110011715398		Not classified	N/A		None
Not Assigned	MCS-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	B0585	9999011715398		Not classified	N/A		None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0589	2350008087100	TM09599A-24P/3 Section 3	IVS cameras and radio set are sensitive and should be shipped separate as sensitive, fragile cargo	Remove IVS cameras before wash down	None	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0589	2430015818572	TM09599A-24P/3 Section 3	IVS cameras and radio set are sensitive and should be shipped separate as sensitive, fragile cargo	Remove IVS cameras before wash down	None	None
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0595	6110012732387	SL-3: SL-3-09124A W/CH 1	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	NA	None.	NA
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0600	6110012726953	SL-3: SL-3-09124A W/CH 1	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	NA	None.	NA
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0605	6110012726952	SL-3: SL-3-09124A W/CH 1	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	NA	None.	NA
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0608	6230012541666	SL-3: SL-3-09049A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	NA	None.	NA
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0626	421001494642	TM 10824A-14&P, PAGE G2	Not Classified	NA	System is integrated on a HMMWV, ship as a single item.	NA
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0626	4210015696073	TM 10840B/11806A-OI, PAGES WP 0034	Not Classified	NA	System is integrated on a HMMWV, ship as a single item.	NA
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0626	4210015791563	TM 10840B/11806A-OI, PAGES WP 0034	Not Classified	NA	System is integrated on a HMMWV, ship as a single item.	NA
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0635	6230011701408	SL-3: SL-3-08857A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	NA	None.	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0640	6230015308890	SL-3: SL-3-11120A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-11120A	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0647	3830014828569	N/A	Not Classified	N/A	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0675	4930010940026	SL-3-07391B	Not Classified	If fuel has been introduced to the system, rubber products cannot be returned to CONUS. Disposition instructions for 600 GPM Pumps (B1583) and Filter Separators are provided separately under the respective TAMCNs.	If fuel has been introduced to the system, rubber products cannot be returned to CONUS. Disposition instructions for 600 GPM Pumps (B1583) and Filter Separators are provided separately under the respective TAMCNs.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0676	4320011101993	SL-3-08936A	Not Classified	N/A	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0685	4930011139173	SL-3-06996C	Not Classified	If fuel has been introduced to the system, rubber products cannot be returned to CONUS. Disposition instructions for 600 GPM Pumps (B1583) and Filter Separators are provided separately under the respective TAMCNs.	If fuel has been introduced to the system, rubber products cannot be returned to CONUS. Disposition instructions for 600 GPM Pumps (B1583) and Filter Separators are provided separately under the respective TAMCNs.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0695	6640013990483	TM 10188A-14&P/1, PAGE C36	Not Classified	N/A	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B0696	6630015341774	TM 11520A-OI, PAGE 0026-001	Not Classified	N/A	N/A	None
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0730	6115012853012	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0891	611501275061	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0891	6115015617455	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	AMMPS GENERATOR: NOT IN USMC INVENTORY YET!!!!	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0921	6115012747392	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	Yes	B0930	6115015310571	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0953	6115001181240	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0953	6115012747389	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0953	6115014619335	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0953	6115015617718	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	AMMPS GENERATOR: NOT IN USMC INVENTORY YET!!!!	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0971	6115014620290	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0980	6115014351565	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B0980	6115014351567	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	THIS IS THE DC MODEL OF THE B0980; CORRECT TAMCN FOR THIS NSN IS B0106, NOT B0980!!!!	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1016	6115012747395	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1016	6115014620292	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1016	6115015617895	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete".	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	AMMPS GENERATOR: NOT IN USMC INVENTORY YET!!!!	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1021	6115012747390	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL-3 complete.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	None.	NA

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1021	6115014620291	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL 3 complete.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1021	6115015617788	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL 3 complete.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	AMMPS GENERATOR: NOT IN USMC INVENTORY YET!!!!	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1045	6115001339101	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL 3 complete.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1045	6115010366374	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL-3 complete.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1045	6115012961463	SL-3: SL-3-6115	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL-3 complete.	In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not	SL-3: SL-3-6115	NA
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1082	3805011504795	N/A	REPLACED BY THE B0078	REPLACED BY THE B0078	REPLACED BY THE B0078	REPLACED BY THE B0078
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1082	3805013036152	N/A	REPLACED BY THE B0078	REPLACED BY THE B0078	REPLACED BY THE B0078	REPLACED BY THE B0078
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1082	3805015736518	N/A	REPLACED BY THE B0078	REPLACED BY THE B0078	REPLACED BY THE B0078	REPLACED BY THE B0078
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1135	4930011149930	SL-3-07387C	Not Classified	If fuel has been introduced to the system, rubber products cannot be returned to CONUS.	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1139	4930014621304	TM 10596A-O/A, WP 32 & 33	Not Classified	If fuel has been introduced to the system, rubber products/hoses cannot be returned to CONUS.	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1140	4610013644485	N/A	Not Classified	N/A	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1170	6675015634405	N/A	No	No	None	No Change
Not Assigned	MCS-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	B1281	6230014658931		Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back "SL-3 complete"	NA	None.	NA
16	MCS-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	B1291	4230013463122	POP is in FP 12112A	No	No	None	SSRI Complete
16	MCS-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	B1291	4230014921540	POP is in FP 12112A	No	No	None	SSRI Complete
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1298	1055012035883	TM 08982A-14&P/2B Chap 4 Section 1	All Class V should be removed and shipped separately	Remove all Class V prior to wash down	N/A	None.
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1300	2320013122616	N/A	Not Classified	N/A	N/A	None.
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1320	9905003759180	OBSELETE REPLACED BY NSN 9905011867253	Not Classified	N/A	N/A	None.
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1320	9905011867253	SL-3-01291B	Not Classified	N/A	N/A	None.
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1420	6630013479670	UURI TM01461B-12&P/1, PAGE F-2	Not Classified	N/A	N/A	None.
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1420	6630013495245	N/A	Not Classified	N/A	N/A	None.
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1570	4930011825028	SL-3-03707F	Not Classified	If fuel has been introduced to the system, rubber products cannot be returned to CONUS.	If fuel has been introduced to the system, rubber products cannot be returned to CONUS.	None.

PG	PMM	MCS C POC for Reset Confirmation & ELP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1580	4320015478729	N/A - THIS IS A 150GPM PUMP	Not Classified	System must be certified gas free prior to shipment to CONUS.	If fuel has been introduced to the system, rubber products cannot be returned to CONUS.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1580	4930012404579	TM09003A/09002A-15&P/1, PAGES 1-2 & C5-C8	Not Classified	System must be certified gas free prior to shipment to CONUS.	If fuel has been introduced to the system, rubber products cannot be returned to CONUS.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1581	4320011563873	N/A - THIS IS A 125GPM PUMP	Not Classified	System must be rinsed and purged prior to shipping to CONUS.	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1581	4320011900417	N/A - THIS IS A 125GPM PUMP	Not Classified	System must be rinsed and purged prior to shipping to CONUS.	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1581	4320013181853	TM 09444A/08990A-15&P/1, PAGES 1-2 & C1-C8	Not Classified	System must be rinsed and purged prior to shipping to CONUS.	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1581	4320013571930	N/A - THIS IS A 125GPM PUMP	Not Classified	System must be rinsed and purged prior to shipping to CONUS.	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1582	4320013359671	DRMO-PHASED OUT	Not Classified	N/A	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1583	4320015336417	TM 11982A-OI/1, PAGES WP 0130 & WP 0131	Not Classified	System must be certified gas free prior to shipment to CONUS.	NSNs 4320-01-533-6417, 4930-01-392-7579 and 4320-01-546-6117, return to Depot MCLC Albany. NSN 4320-01-588-9165, provide to OPFOR deficient unit. NSNs 4930-01-103-7609 and 4320-01-215-7671, DRMO in country.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1583	4930013927579	DRMO-PHASED OUT	Not Classified	System must be certified gas free prior to shipment to CONUS.	NSNs 4320-01-533-6417, 4930-01-392-7579 and 4320-01-546-6117, return to Depot MCLC Albany. NSN 4320-01-588-9165, provide to OPFOR deficient unit. NSNs 4930-01-103-7609 and 4320-01-215-7671, DRMO in country.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1585	4330001778485	DROM-PHASED OUT	Not Classified	System must be certified gas free prior to shipment to CONUS.	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1585	4330015338221	TM 11224A-OI, PAGES WP 0030 & WP 0031	Not Classified	System must be certified gas free prior to shipment to CONUS.	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1620	4320014764795	SL-3-00970D	Not Classified	System must be rinsed and purged prior to shipping to CONUS.	N/A	None.
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1645	4110011521946	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL-3 complete.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1645	4110014689792	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material. Ship equipment back SL-3 complete.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1710	4110011079078	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1713	4250013382707	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B1713	4250014117240	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1720	5420011391503	SL-3-08710A	N/A	NO	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1775	3830011715776	N/A	REPLACED BY THE B0081	REPLACED BY THE B0081	REPLACED BY THE B0081	REPLACED BY THE B0081
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1785	3895014538573	TM 5-3895-383-10 Sections 2 and 3	Not Classified	NONE	None.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1785	3895015508369	TM 5-3895-383-10 Sections 2 and 3	Not Classified	NONE	None.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1785	3895015733847	TM 5-3895-383-10 Sections 2 and 3	Not Classified	NONE	None.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1830	3695006796914	N/A	Not Classified	N/A	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1922	3805011531854	N/A	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B1922	3805015820743	N/A	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER	OBsolete IN 2012, BEING REPLACED BY A NEW SCRAPER
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1942	4910015507118	TM 08165B-OR	Not classified	N/A	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B1942	5180010619292	DRMO-PHASED OUT	Not classified	N/A	N/A	None.
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B1951	4940012355080	SL-3-09018A	N/A	Nothing beyond standard procedures.		
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B2006	4120005757200	SL-3: SL-3-07768A W/CH 1	Not classified	N/A	N/A	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2030	1670009023080	N/A	Not classified	None.	None.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2035	3940011832118	N/A	Not classified	None.	None.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2085	5430012404578	SL-4-09002A Page 1	Not classified	System must be certified gas free prior to shipment to CONUS.	If fuel has been introduced to the system, rubber products cannot be returned to CONUS.	None.
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2086	5430012039971	TM 09444A/08990A-15&P/1 W/CH 1-2	Not classified	System must be rinsed and purged prior to shipment to CONUS.	N/A	None.
Not Assigned	MCS C-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	B2118	6675010883181					
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2120	6675012737812	N/A	Not classified	N/A	N/A	None.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2127	3830015042618	TM091998-OR Chapter 6 Workpackage 002400	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2130	5430011706984	SL-3-01034	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2130	5430013594774	SL-3-01034	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2130	5430015405357	SL-3-01034	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2131	4610011207526	SL-3-09495A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2133	4610011406775	SL-3-09721A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2134	4610011406776	SL-3-09481A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2135	4610011207522	SL-3-09563A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2136	4610011237705	SL-3-09483A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2137	4610011207525	SL-3-09496A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2139	4320011207524	SL-3-09484A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2150	6635006413643	N/A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2150	6635014891524	N/A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2170	3990008566245	N/A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2190	5180012899051	N/A	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2210	5180002932873	DRMO-PHASED OUT	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2210	5180002932875	DRMO-NOT MARINE CORPS	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2210	5180014472199	SAC1 / NO SL-3 OR TM	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2210	5180015518250	TM 11411A-OR	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2210	5180015877997	TM 11411A-OR	Not Classified	NONE	None	None
Not Assigned	MCS C-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	No	B2220	9999005405741		Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2238	5180012547723	N/A	Not Classified	NONE		None
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B2240	5180005961531	SL-3: SI-3-01204A	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2250	5180015508112	TM 11423A-OR	Not Classified	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2260	5180005961547	DRMO-PHASED OUT	Not Classified	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2260	5180015508116	TM 11422A-OR	Not Classified	NA	None.	None
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	No	B2280	5180005961474	NA	Neither this TAMCN nor any SSRI or UURI items are classified sensitive material.	NA	None.	NA
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2335	5180007540661	N/A	Not Classified	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2370	5180015513550	TM 00425B-OR	Not Classified	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2394	4320015336418	TM 11986A-OI/L, PAGES WP 0130 & WP 0131	Not Classified	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2395	4320013774577	SL 3-09854A	Not Classified	NA	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2410	5180014280959	SL-3-10259A PCN 123102590 00	N/A	NO	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2420	5180014292683	SL-3-10258A PCN 123 102580 00	N/A	NO	None.	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2460	2410012541667	TM 09026A-OR Work Package 001500 And 001600 SL-3-09085A 3rd & 4th echolon	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2460	3805015735861	TM 09026A-OR Work Package 001500 And 001600 SL-3-09085A 3rd & 4th echolon	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2462	2410011551588	N/A	REPLACED BY THE B0060	REPLACED BY THE B0060	REPLACED BY THE B0060	REPLACED BY THE B0060
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2462	2430015330934	N/A	REPLACED BY THE B0060	REPLACED BY THE B0060	REPLACED BY THE B0060	REPLACED BY THE B0060

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2464	3805013151091	TM 09026A-OR Work Package 001500 And 001600 SL-3-09085A 3rd & 4th echolon	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2464	3805015735867	TM 09026A-OR Work Package 001500 And 001600 SL-3-09085A 3rd & 4th echolon	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2483	3805015147166	N/A	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2483	3805015733850	N/A	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2561	3930014862151	TM 10794B-OR/A Work package 0018 00	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2561	3930015080886	TM 10794B-OR/A Work package 0018 00	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2561	3930015735868	TM 10794B-OR/A Work package 0018 00	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2565	2330015183809	TM 11026-OI/A Work package 0057 00	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2565	2330015470272	TM 11026-OI/A Work package 0057 00	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2566	3930012756420	N/A	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2566	3930014783519	N/A	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2566	3930015330855	N/A	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2566	3930015735873	TM 11299A-OD Work Package 0039	Not Classified	NONE	NONE	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2567	3805012793635	N/A	REPLACED BY THE B0063	REPLACED BY THE B0063	REPLACED BY THE B0063	REPLACED BY THE B0063
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	Yes	B2567	3805015735881	N/A	REPLACED BY THE B0063	REPLACED BY THE B0063	REPLACED BY THE B0063	REPLACED BY THE B0063
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2605	4610014886961	TM 10802A-OI/1A VOL 1, PAGES WP 0046 & WP 0047	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2628	4610013664640	DRMO-PHASED OUT	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2630	6630014772395	TM 10-6630-222-12&P, PAGES WP 0026	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2631	5430011069677	N/A	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS.	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2631	5430012004831	N/A	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS.	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2631	5430013861544	N/A	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS.	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2632	5430013517813	N/A	Not Classified	If system has been placed in-service or is not in original packaging, system cannot be returned to CONUS.	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2685	3431014984423	TM 04055D-OI/1 Work package 000200 Pgs 00020031-00020050	Not Classified	NONE		None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2686	3431015050248	TM 10926A-OI/1 worl package 002	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2687	3431015050888	TM 10927A-OI/1 Work package 002 00	Not Classified	NONE	None	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2705	2590011551587	N/A	REPLACED BY THE B0079	REPLACED BY THE B0079	REPLACED BY THE B0079	REPLACED BY THE B0079
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B2730	8110008566243	SAC1 - NO SL-3 OR TM	Not Classified	N/A	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	B5000	6665015314689	N/A	Not Classified	N/A	N/A	None
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B7001	6625014385312	DP 11072A	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B7001	6625015260788	SL-3-11072B	N/A	N/A		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	B7900	5180015468026	SL-3-11390A	N/A	N/A		
PM MRAP	MCS C-PMM-154	Mark Billow - Dial In	14-Nov; 0900 - 1000	Yes	C0005	5895015314671	Draft SL-3 in-work	This TAMCN is not classified as sensitive. There is no SSRI or UURI items that are classified sensitive. This equipment in its entirety should be shipped to MCLB Albany.	DO NOT POWER WASH; contains sensitive electronics which water can damage. Use compressed air.	Upon MCLB Albany Receiving equipment from theater, PM-CIED should be contacted so a complete inventory assessment can be performed to ascertain the equipments reliability status. POC: Mr. Mark J. Billow, PM-CIED, (703) 462-4961.	This equipment is not a program of record and is not owned by any using unit. Therefore no configuration for fielding is required.
13	MCS C-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	Yes	C0008	5805015315590	No SL-3	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No	Obsolete replaced by the EoF-MM TAMCN C01047B. DP 5500 applies.	No configuration differences.
13	MCS C-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	Yes	C0019	6910015403090	No SL-3	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No	Obsolete replaced by the EoF-MM TAMCN C01047B. DP 5500 applies.	No configuration differences.

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
13	MCSC-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	No	C0020	6910015403064	No SL-3	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No	Obsolete replaced by the EoF-MM TAMCN C01047B. DP 5500 applies.	No configuration differences.
13	MCSC-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	No	C0104	1367015794067	SL-3 is under development. Units may use TM 11809-OI Vols I-III to ID SL-3 items.	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No	In FY 11, 20 systems were fielding to MEF FWD. Two (2) of these 20 were shipped to MEF FWD Bahrain which I am assuming is a part of the 16 on hand units. Four (4) of the 20 units were not issued and are still at the MEF FWD ERDT.	No configuration differences.
PEO LS	MCSC-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	C0114	4210015583687	N/A	This TAMCN IS NOT classified sensitive. No SSRI or UURI items associated to this TAMCN. Disassociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None.	None.
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C2032	6665997259996	DP 09717C				
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C2104	6665015522704	TM 11568A-OR				
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C2108	6665014386963	DP 10434A				
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C3409	6230015250794	No publications for this PEI.				
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C3411	8340014598167	TM is in development.				
13	MCSC-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	No	C4120	9999014642285	SL-3-10617A	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No	Obsolete replaced by the EoF-MM TAMCN C01047B. DP 5500 applies.	No configuration differences.
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C4265	1080014750694	TM 5-1080-250-12&P				
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C4266	1080014750696	TM 5-1080-250-12&P				
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C4267	1080014750697	TM 5-1080-250-12&P				
Not Assigned	MCSC-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	C4432	5411012066036					
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	C4765	4210001072082	DRMO-OBSOLETE	Not Classified	N/A	N/A	None
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	C4765	4210012052246	SL-3-07661	Not Classified	N/A	N/A	None
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	C4765	4210013549893	SL-3-07661	Not Classified	N/A	N/A	None
15	MCSC-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	C4906	3990011907165	DROM-OBSOLETE	No	No	None	N/a
Not Assigned	MCSC-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	C5105	5411012066037					
16	MCSC-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C5269	6665015069002	TM 10942A-OI/1	No	Assets will be returned to MEF CSP UIF's for disposition	N/A	
16	MCSC-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	C5810	7360332012934	SL-3-10879A	NO	None	C5810 will be replaced by EFK staring 2D QTR FY12	N/A
16	MCSC-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	C5820	7360000822153	No publications for this PEI.				
Not Assigned	MCSC-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	C6115	5411012066077					
16	MCSC-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	C6621	7310012957479	TM 09211A-14&P				
16	MCSC-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	C6621	7310014428340	TM 09211A-14&P				
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7001	4910015592405	SL-3-10844B		Only the outside can be washed.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7007	4940015521599	TM 11446A-OI		Only the outside can be washed.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7023	4910014602822	TM 10575A-12&P	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.	This items is in the process of being replaced by a new item.	
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7033	4940013338471	SL-3-4940		Only the outside can be washed.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7035	5180011994018	SL-3-08603B	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7038	4910015975999	This was a I MEF procurement	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7039	0000000000000	This was a II MEF procurement	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7042	5825014731977	TM 10215B-OI	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7061	4910011249123	TM-10604A-14&P/1	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	Yes	C7072	4910013831130	TM 09875A-24&P/1	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	Yes	C7072	4910015978824	TM 09875A-24&P/1	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.		This NSN has not yet been fielded.	
16	MCSC-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7073	4910012388115	POP - SI 10025A-OD/1		Only the outside can be washed.		

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	C7110	5836015016979	SL-3-10902B	No sensitive equipment	Once the shelter is closed and locked, it can be agriculturally washed. The air conditioning units should be washed Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out. In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not to overspray onto electrical components.	This gear should be considered pilferable and should not be handled by foreign nationals if possible	same configuration
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	C7110	5836015253637	SL-3-10902B	No sensitive equipment	Once the shelter is closed and locked, it can be agriculturally washed. The air conditioning units should be washed Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out. In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not to overspray onto electrical components.	This gear should be considered pilferable and should not be handled by foreign nationals if possible	same configuration
12	MCS C-PMM-123	Karen Hartman & GySgt Hicks	17-Nov; 1030 - 1800	No	C7110	5836015450581	SL-3-10902B	No sensitive equipment	Once the shelter is closed and locked, it can be agriculturally washed. The air conditioning units should be washed Water (not to exceed 60 PSI) can be used on the external portions of the ECU's. The evaporator coil, condenser coil, and control cubicle should cleaned with compressed air. Coils need to be cleaned from the inside out in order to properly clean them out. In order to avoid damage, generator sets should be washed down with the control panel cover closed, in the event it is necessary to clean the control panel or inside the actual control cubicle this should be done by hand with a dry cloth, compressed air or vacuum system. During the external wash down the exhaust port should be taped over to prevent water intrusion. When the set doors are opened to clean inside the set, care must be taken so that water does not contact any electrical components. This often dictates hand cleaning (damp rags, compressed air, vacuums). Low to medium pressure water can be used in and around the engine portion of the generator as long as extreme care is taken not to overspray onto electrical components.	This gear should be considered pilferable and should not be handled by foreign nationals if possible	same configuration

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7900	412001541688	SL-3-11300A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7901	4940015223536	DP 11053A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.		This NSN was specifically fielded for Afghanistan, and should be DRMO'd if not longer required there.	
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7901	4940015515941	DP 11053A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.		This NSN was specifically fielded for Afghanistan, and should be DRMO'd if not longer required there.	
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7901	4940015683817	SL-3-11053C & SL-3-11522A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.			
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7903	4220015041223	SL-3-11095A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.	Commercial item that is better to buy at a low cost than to reset. Unit cost is less than \$2k.	
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7904	4940015219685	SL-3-11052A		Only the outside can be washed.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7905	4940015504312	SL-3-11415A		Only the outside can be washed.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7907	4940015637780	SL-3-11589A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7908	4930015497112	SL-3-11411A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Nothing beyond standard procedures.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7908	4930015497112	SL-3-11411A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.	No assets should be DRMO'd due to shortage of assets.	
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7911	4940015504900	SL-3-11515A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.	No assets should be DRMO'd due to shortage of assets.	
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7912	3470015752955	SL-3-11762A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	DO NOT WASHDOWN - CLEAN BY HAND.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7913	4940015659593	SL-3-11614A		Only the outside can be washed.		
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7915	5180014931664	POP 00456A/00456B				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7915	5180015544224	SL-3-11668A				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7920	4910014865131	DP10791A				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7920	4910015350413	SL-3-10791B				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7920	4910015694435	SL-3-10791C				
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C7930	5180015187339	SL-3-11024A				
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8004	6515090006457	SSRI-UURI- All items are SSRI. Refer to Medical logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALs/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALs and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALs and ADAL-AMAL banded and intact - Roll back to MEDLOG to CONUS after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8007	6515090006486	SSRI-UURI- All Items are SSRI. Refer to Medical logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.auxt.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
15	MCS C-PMM-153	John Padden	16-Nov; 0815 - 1700	Yes	C8010	5411015757079	NA	No	N/A	None	N/A
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8600	6515090006459	SSRI-UURI- All Items are SSRI. Refer to Medical logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.auxt.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8604	6515090006455	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8614	6515090006454	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8624	6515090006496	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8628	6515090006494	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8638	6515090006473		TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALs and ADAL-AMAL banded and intact - Roll back to MEDLOG to CONUS after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8640	6515090006472	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALs/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALs and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to wash down.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALs and ADAL-AMAL banded and intact - Roll back to MEDLOG to CONUS after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8644	6515090006495	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.asp . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8648	6515090006497	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.asp . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8656	6515090006501	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.auxt.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8685	6515090006498	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.auxt.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8686	6515090006500	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8694	6515090006480	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8698	6515090006477	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8700	6515090006483	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8715	6515090001996	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8740	6515090006484	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
16	MCS C-PMM-163	Michael Roberts	18-Nov; 0915 - 1415	No	C8745	6515090002014	SSRI-UURI- All items are SSRI. Refer to Medical Logistics On-Line Database for a list of equipment components, which are too numerous to list here at https://www.pmcbrnsupport.com/kb/default.aspx . The Medical Logistics On-line Database also provides packing instructions for most AMALS/ADAL (19 of 30 have packing lists). Each AMAL/ADAL was fielded with ECS Cans to pack medical equipment and supplies regardless if there is a packing list or not. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	Medical equipment and supplies must be free of blood and body fluids. Fabric or other material stained with blood or other body fluids must be disposed of as biological waste. All medical equipment and supplies free of contaminants, must be packed in waterproof ECS cases (provided with each AMAL/ADAL) prior to washdown.	Consumables- Consume, dispose, or "donate" if authorized. Cannot validate the care and storage of materiel. Standard practice is to not accept materiel once issued. Even if returned to CONUS would have to be disposed of. Pharmaceuticals- Do not retrograde. Utilize USAMMA/DLA Reverse Distribution Program ("Guaranteed Returns") or dispose. Cannot validate the care and storage of materiel. Equipment- Serviceable equipment (as determined by a BMET), provide list to PM CSE for recommended disposition; Obsolete and unserviceable, DRMO in theater. Rationale - There may be some medical equipment that is worth returning to stock to fill a deficiency or to maintain in support of min/max inventory reset. Complete AMALS and ADAL-AMAL banded and intact - Roll back to MEDLOG after coordination with PM CSE. Rationale - Supports inventory reset.	TAMCN is not fielded differently at the home station units than is theater.
16	MCS C-PMM-161	Michael Roberts	18-Nov; 0915 - 1415	No	C9657	4910011174344	SL-3-08491A	TAMCN is not classified sensitive. There are no SSRI or UURI items that are classified sensitive.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Commercial item that is better to buy at a low cost than to reset. Unit cost is less than \$4k.	
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	Yes	D0002	2330014838000	BII Identified in TM 10770-01	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	TOECR Submitted to establish MEF Allowances.	None
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0003	2320015305676	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0003	2320015305677	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0004 and all NSN's under D0004. NSN's are now carried under TAMCN D0003	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0003	2320015519433	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0004 and all NSN's under D0004. NSN's are now carried under TAMCN D0003	

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0003	2320015520273	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0005	2320015305678	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0005	2320015305681	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0004 and all NSN's under D0006. NSN's are now carried under TAMCN D0005	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0005	2320015519434	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0004 and all NSN's under D0006. NSN's are now carried under TAMCN D0005	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0005	2320015522762	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0005	2320015534118	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0004 and all NSN's under D0006. NSN's are now carried under TAMCN D0005	

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0007	2320015305684	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0105 of TM 10632A-OD. AAL is located in WP 0106 of TM 10632A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0007	2320015305685	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0105 of TM 10632A-OD. AAL is located in WP 0106 of TM 10632A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0008 and all NSN's under D0007. NSN's are now carried under TAMCN D0005	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0007	2320015520250	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0105 of TM 10632A-OD. AAL is located in WP 0106 of TM 10632A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0007	2320015520269	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0105 of TM 10632A-OD. AAL is located in WP 0106 of TM 10632A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	DELETE TAMCN D0008 and all NSN's under D0007. NSN's are now carried under TAMCN D0005	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0009	2320015305693	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0095 of TM 11165A-OD. AAL is located in WP 0096 of TM 11165A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	None	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0009	2320015311975	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0095 of TM 11165A-OD. AAL is located in WP 0096 of TM 11165A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	None	

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruity to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0009	2320015520403	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0095 of TM 11165A-OD. AAL is located in WP 0096 of TM 11165A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	None	
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0010	5180015204069	This TAMCN does not have an SL-3. It has a Tools Components Listing in the MTVR IETM TM 10629-DVD in Figure 233.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0011	2510015352385	N/A	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0011	2510015380714	N/A	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0012	5180015204070	This TAMCN does not have an SL-3. It has a Tools Components Listing in the MTVR IETM TM 10629-DVD in Figure 232.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0013	2320015305687	This TAMCN does not have a SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0095 of TM 11165A-OD. AAL is located in WP 0096 of TM 11165A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0013	2320015520282	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0095 of TM 11165A-OD. AAL is located in WP 0096 of TM 11165A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCSC-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0015	2320014652300	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0141 of TM 10633A-OD. AAL is located in WP 0142 of TM 10633A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	Delete, NSN not issued to the fleet	

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0015	2320015305691	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0141 of TM 10633A-OD. AAL is located in WP 0142 of TM 10633A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0015	2320015520268	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0141 of TM 10633A-OD. AAL is located in WP 0142 of TM 10633A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	Delete, NSN not issued to the fleet	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0015	2355015535400	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0141 of TM 10633A-OD. AAL is located in WP 0142 of TM 10633A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31	Delete, NSN not issued to the fleet	
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	No	D0015	2355015902719	Not being developed. USMC will return these temp loaned assets to the Army at some point.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0016	2330013875426	BII Identified in TM 9-2330-392-14&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0017	2330015435794	BII Identified in TM 9-2330-392-14&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0018	5180015288089	N/A				
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0022	2320015187332	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0023	2355015626152	None	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED CAISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.	The MAXPRO Ambulance variant was loaned to the USMC and should be returned to the US Army if not already returned.	All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0023	2355015831029	TBD	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015198173	SL-3-11291A	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. and in accordance with SPAWAR Agricultural Washdown guidelines. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015322174	SL-3-11291A	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015525565	SL-3-11202D	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015643420	SL-3-11202I	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015672879	NONE			These vehicles were loaners from the US Army and should be returned.	

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015798929	SL-3-11202I	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0025	2355015812392	SL-3-11202D	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015198172	SL-3-11291A	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015292246	NONE	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015525199	SL-3-11291D	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.

PG	PMM	MCS C POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for dissociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015643423	SL-3-11291J	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015798920	SL-3-11291J	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015798931	SL-3-11291D	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0027	2355015811076	SL-3-11291D				
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0030	2320014133739	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0030	2320015187330	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	Only one base M1151 procured in USMC. Possible wrong NSN.	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0030	2320015231316	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	Unknown NSN	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0030	2320015402038	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0031	2320015401993	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0033	2320015402007	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0034	2320015402017	BII Identified in TM 11033-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0035	2330013035197	BII Identified in TM 11775A-OR	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	Coordinating with Army to use their Depot. Send WIR to LOGCOM Albany, GA for disposition instructions.	None

PG	PMM	MCS C POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	No	D0036	2355015759632	SL-3-11803A	Vehicle is not considered sensitive. Several of the GFE components "are" considered sensitive and should be handled IAW established policy/procedures.	Use a high pressure washer for cleaning exterior of engine, capsule and body. Rinse with hot water, if available. An ordinary garden hose, with nozzle, may be used if other equipment is not available. Ensure a complete rinsing. Do not allow a stream of water to contact Dash, Dashboard Components and other Electrical connections. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.	No Amplifying Comments.	All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PM MRAP	MCS C-PMM-154	Jim Strickland	14-Nov; 0900 - 1000	Yes	D0040	2355015891279	TBD	Multiple radio and communication TAMCNs, computer TAMCNs, etc – please refer to SL-3. The radios (which may contain embedded crypto), computer hard drives, and the crypto need to be shipped IAW SOP and guidance from the EKMS manager.	Follow normal procedures for exterior washdown of Tactical Wheeled Vehicles. Exterior antenna(s) should be removed prior to power-washing. Interior of vehicle contains sensitive electronics which water can damage. Use compressed air and a vacuum to dust and clean. Damp rags may be used to wipe areas clean. Guidance contained in N65236-MRAPFOV-AGWASH-GUIDE-1.0 AGRICULTURAL WASHDOWN (AGWASH) GUIDE FOR THE MINE RESISTANT AMBUSH PROTECTED (MRAP) FAMILY OF VEHICLES (FOV) AND ASSOCIATED C4ISR SYSTEMS INTEGRATED AT SPAWAR SYSTEMS CENTER ATLANTIC.		All of the itmes listed as SSRI will be associated to the vehicle (Not loaded to MALS/CMRS). SEI used for certain types of missions/vehicles, like the GYROCAM or VRC-103, are considered UURI and will be added to the unit's property records (MAL/CMR). This allows the commander choose where and how to employ a unique capability without having it on every vehicle.
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0080	2330005422831	BII Identified in TM 9-2330-247-14	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0085	2330011018434	BII Identified in TM 9-2330-202-148&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0085	2330013590080	BII Identified in TM 9-2330-202-148&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0085	2330014731623	BII Identified in TM 9-2330-202-148&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Component TAMCN asset. PM COMM asset not PMM-151 Motor Transport.	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0100	4940004496689	BII Identified in TM 10770-OI	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0187		BII Identified in TM 10770-OI	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Duplicate to D0187 line.	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0187	2320013808604	BII Identified in TM 2320-10/6B	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0188	1	Unknown TAMCN/Not PEO LS	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Delete. Error in TFSMS. TAMCN is D0187.	None.
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0195	3990013077676	BII Identified in TM 9-3990-206-148&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	No repair beyond Field Level Maintenance	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0195	3990015371045	BII Identified in TM 9-3990-206-148&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	No repair beyond Field Level Maintenance	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0201	2340014652533	BII Identified in TM-09580B-10	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0209	2320011775167	BII Identified in TM 08780B-10. Obsolete equipment/TAMCN and should not be returning	DEMIL Code D if disposed of in theater.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0209	2320014173180	BII Identified in TM 08780B-10. Obsolete equipment/TAMCN and should not be returning	DEMIL Code D if disposed of in theater.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	Yes	D0215	2330015378217	BII Identified in TM 08089B-OI/1A	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	Yes	D0215	2330015593657	BII Identified in TM 08089B-OI/1A	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None

PG	PMM	MCS C POC for Reset Confirmation & ELM P Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for dissociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0235	2330014424975	BII Identified in TM 07862C-OI or TM 5-2330-378-14&P.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0235	2330015344570	BII Identified in TM 07862C-OI or TM 5-2330-378-14&P.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0475	5180012168655	BII Identified in SL-3-11900A	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0478	5180009991166		This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0478	5180012471046		This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0751	5180014772399	This TAMCN does not have an SL-3. It has a Tools Components Listing in the MTVR IETM TM 10629-DVD in Figure 226.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0752	5180014772390	This TAMCN does not have an SL-3. It has a Tools Components Listing in the MTVR IETM TM 10629-DVD in Figure 227.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0850	2330008986779	BII Identified in TM 9-2330-202-14&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0850	2330013725641	BII Identified in TM 9-2330-202-14&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0860	2330001418050	BII Identified in TM 9-2330-213-14&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D0861	2330015045014	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI/BII is located in Appendix D of TM 10921A-13P/A. There is no AAL for the	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0876	2320011760469	BII Identified in TM 09470A-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0876	2320014175294	BII Identified in TM 09470A-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0877	2320011766928	BII Identified in TM 08780B-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Each D0877 will require a D0209 FPU IOT be shipped back to CONUS	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0877	2320014178144	BII Identified in TM 08780B-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Each D0877 will require a D0209 FPU IOT be shipped back to CONUS	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0878	2320011760467	BII Identified in TM 08780B-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Each D0877 will require a D0209 FPU IOT be shipped back to CONUS	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0878	2320014175293	BII Identified in TM 08780B-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	Each D0877 will require a D0209 FPU IOT be shipped back to CONUS	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0880	2330005422039	BII Identified in TM 9-2330-267-14&P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None

PG	PMM	MCS C POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0880	2330011087367	BII Identified in TM 9-2330-267-148P	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D0881	2320013920293	BII Identified in TM 087808-10. Obsolete equipment/TAMCN and should not be returning.	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	PEOLS-LVSR	Joanne Beck	15-Nov; 1430 - 1600	No	D0886	2320015427628	This TAMCN does not have SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Appendix "B" TM 11313-OR. AAL is located in Appendix "C" of TM 11313-OR.				Vehicles fielded CONUS will not include the SSRI which are OEF specific. In addition, in theory, the armor for D0886 is modular and may be removed to reduce sustainment costs.
PEO LS	PEOLS-LVSR	Joanne Beck	15-Nov; 1430 - 1600	No	D0887	2320015429941	This TAMCN does not have SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Appendix "B" TM 11316A-OR. AAL is located in Appendix "C" of TM 11316A-OR.				
PEO LS	PEOLS-LVSR	Joanne Beck	15-Nov; 1430 - 1600	No	D0887	2320015927353	This TAMCN does not have SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Appendix "B" TM 11316A-OR. AAL is located in Appendix "C" of TM 11316A-OR.				
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1001	2310013723934	BII Identified in TM 2320-10/6B	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1001	2310013808225	BII Identified in TM 2320-10/6B	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1059	2320000508905	Obsolete equipment/TAMCN (TM 9-2320-272-10)	DEMIL Code D if disposed of in theater.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D1062	2320014652182	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI/BII is located in Work Package (WP) 0111 of TM 10629A-OD. AAL is located in WP 0112 of TM 10629A-OD.			This item does not exits on the EDL and is not deployed in theater.	
PEO LS	MCS C-PMM-MTVR	Howard Waiters	15-Nov; 1430 - 1600	No	D1063	2320015640834	This TAMCN does not have an SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and is shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Work Package (WP) 0137 of TM 10920A-OD. AAL is located in WP 0138 of TM 10920A-OD.	N/A	All items should be wash IAW MCRP 4-11.3G, Unit Embarkation Handbook, Chapter 9 and Armed Forces Pest Management Board Technical Guide No. 31		
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1064	4210011379943	BII Identified in SL-3-08674A and SL-3-08952A	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1072	2320000508970	Obsolete equipment/TAMCN (TM 9-2320-272-10)	DEMIL Code D if disposed of in theater.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1072	2320010478756	Obsolete equipment/TAMCN (TM 9-2320-272-10)	DEMIL Code D if disposed of in theater.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1125	2320013808229	BII Identified in TM 2320-10/6B	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1158	2320014559593	BII Identified in TM 2320-10/6B	DEMIL Code D if disposed of in theater.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1161	2320015312701	BII Identified in TM 2320-OR/A	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	D1212	2320012064078	Obsolete equipment/TAMCN (TM 9-2320-272-10)	This TAMCN IS NOT classified sensitive. No SSI or UURI items associated to this TAMCN. Dissociating TAMCN Not Required.	No special Agriculture wash down instruction apply. Apply standard local SOP.	None.	None.
PEO LS	PEOLS-LVSR	Joanne Beck	15-Nov; 1430 - 1600	No	D1214	2320015430651	This TAMCN does not have SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Appendix "B" TM 11321A-OR. AAL is located in Appendix "C" of TM 11321A-OR.				Vehicles fielded CONUS will not include the SSRI which are OEF specific. In addition, in theory, the armor for D0886 is modular and may be removed to reduce sustainment costs.
PEO LS	PEOLS-LVSR	Joanne Beck	15-Nov; 1430 - 1600	No	D1214	2320015430651	This TAMCN does not have SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Appendix "B" TM 11321A-OR. AAL is located in Appendix "C" of TM 11321A-OR.				
PEO LS	PEOLS-LVSR	Joanne Beck	15-Nov; 1430 - 1600	No	D1214	2320015939122	This TAMCN does not have SL-3. The SL-3 has been replaced by Components of End Item (COEI), Basic Issue Items (BII) and Additional Authorized list (AAL). All COEI and BII remains with and shipped with the TAMCN. All AAL is to be removed from the TAMCN before RESET. COEI and BII are located in Appendix "B" TM 11321A-OR. AAL is located in Appendix "C" of TM 11321A-OR.				
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E0001	5855015629999	TM 11573A-OR/1	No, None	Do Not Spray or wet any Electronic Components	None	N/A
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	Yes	E0004	1220011618888	TAMCN is in Disposal (PD)	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0005	5855014199429		No/No/ N/A/Can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No	Category 3 Equipment - (as extracted from TFSMS) "E00057B There has never been an approved UUNS for this item, no requirement has ever been generated from DC, CD&I to procure this equipment, and this gear has never been procured by Marine Corps System Command. The following note is listed in TFSMS: "OIF/U-UNS ITEM IS NOT A PROGRAM OF RECORD FOR THE USMC (THIS IS AN OIF REQUIREMENT CANNOT DELETE, ENTERED BY AAO COORD)". None of this is correct. This is one of several instances where someone in TFSM erroneously issued a TAMCN for an UUNS that was either not approved or some unit in the operating forces procured an item(s) with unit funds and convinced TFSM to establish a	

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0006	5855015026414	SL-3-11173A PCN123 111730 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
Not Assigned	MCS C-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	E0007	5865015315577					
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0008	5855015583616	SL-3-11499A PCN 123 114990 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0010	6625011123068	NONE	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0012	5855015350971	N/A	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No	Please delete this entire row. Ref'd NSN is for the Tactical Range Thermal Imager (TRTI). TRTI contract was terminated for the convenience of the government / never made it to a fielding MS decision, PMM135 never took delivery of those qtys assoc'd to the (2006) planned production delivery schedule. None are in the MC inventory.	
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0012	5855015732483	N/A				
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0016	6650015837651	SL-3-11901A PCN 123 110910 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0017	1240015341114	SL-3-11064 PCN 123 110640 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0018	1010015912226		No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	Category 2 Equipment		
PM LAV	MCS C-PMM-LAV	CW05 Ron Parks	15-Nov; 1300 - 1430	No	E0019	4933014418678		TAMCN is not classified. No classified SSRI or UURI.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0020	5855015479489	SL-3-11085B PCN 123 110851 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E0025	1010015350989	NSN REPLACED BY 1010-01-584-0703	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		

PG	PMM	MCS POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
13	MCS-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E0025	1010015840703	SL-3 - 11906A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
PM LAV	MCS-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0026	6625012637292					
13	MCS-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E0028	1005015389643	TAMCN is in Disposal (PD)	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS-PMM-141	Anthony Smith & Dell Murray	14-Nov; 1500 - 1730	No	E0036	6675015637465	SL-3-11587A	No, None	No direct water contact on electrical components	None	N/A
Not Assigned	MCS-PMM-091	Stephen Magee	18-Nov; 1415 - 1500	Yes	E0038	6230015523289	SL-3-11452A PCN 123 114520 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No	Category 1 Equipment	
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0039	1385015651626	SL-3-11601A (DRAFT)	None	None	A TOECR has been submitted to change from SAC-3 to SAC-1	N/A
14	MCS-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E0042	1240015666510	Draft TM	No, None	Do not wash, but clean with damp cloth.	None	N/A
14	MCS-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E0042	5860090004433	Draft TM	No, None	Do not wash, but clean with damp cloth.	None	N/A
14	MCS-PMM-141	Dwight Strickland & Dell Murray	14-Nov; 1500 - 1730	No	E0043	2320015535269	SL-3-11472A	No, None	Do Not Spray or wet any Electronic Components	None	N/A
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0044	5850015592664	SL-3-11537A (DRAFT)	N/A	Follow standard procedures	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0045	1385015594872	SL-3-11543A (DRAFT)	N/A	Follow standard procedures	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0046	1385015595502	SL-3-11542A (DRAFT)	N/A	Follow standard procedures	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0047	5180015592933	SL-3-11540A (DRAFT)	N/A	Follow standard procedures	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0049	5180015594338	SL-3-11541A (DRAFT)	N/A	Follow standard procedures	N/A	None
16	MCS-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	E0050	1095000179701	TM 9-1005-237-23&P				
16	MCS-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	E0050	1095015063424	TM 9-1005-237-23&P				
16	MCS-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	E0050	1095015216087	OKC 3S / 500 055760 00				
13	MCS-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E0051	1005070001255	SL-3 - 11416A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	Yes	E0053	5860015447175	No SL-3. Units may use TM 11352A-OI to ID SL-3 items.	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No		No configuration differences.
14	MCS-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	Yes	E0054	1240015723753	Part of E1048	No, None	Do not wash. Clean with damp cloth.	None	N/A
13	MCS-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0055	5865015598728	SL-3-11581A (PCN 12311581000)	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0056	6635015459905	N/A	N/A	Follow standard procedures	N/A	None
15	MCS-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0057	6635015037883	OBSOLETE - DP 11905A/10697A	None	None	Obsolete. A disposal plan has been approved to remove E0057 from inventory.	N/A
13	MCS-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0058	5855015502780	SL-3-11407C PCN 123 114072 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0058	5865015494506	SL-3-11407C PCN 123 114072 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		

PG	PMM	MCS C POC for Reset Confirmation & EIMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0060	6625015756647	SL-3-11764A(PCN 123 117640 00)	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0061	5855015110994	N/A	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0062	5855015597064		No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0063	5855015544673		No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0064	1385015349828	N/A	N/A	Follow standard procedures	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0066	1385015349826	N/A	N/A	Follow standard procedures	N/A	None
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0067	5410015511127		No/No/For SSRI items, can disassociate as reasonable, yet the end-state reqd for E00677B (parent TAMCN); is that all depicted Column 'G' items are configuration complete. / can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is a system of systems (see FP	No		
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0069	6625015528270	SL-3-11464A	No items classified sensitive	No equipment conditions; however, care should be taken when utilizing high pressure wash around generator/ECU area. SL-3 should remain with PEI.		No configuration differences
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0070	2330015528661	SL-3-11464A	No, None	None	None	N/A
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	E0071	2540015464267	N/A	Not Classified	N/A	MCTAGS SHOULD NOT BE REMOVED FROM HMMWVS BUT RETURNED INTACT ON VEHICLES	None
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0073	2540015411934	NONE	Not Classified	N/A	N/A	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	E0074	2540015465079	N/A	Not Classified	N/A	N/A	None
PEO LS	MCS C-PMM-151	Mike Mimms, Jerrille, Doug Kosky, & Mike Jackson	15-Nov; 0800 - 1200	No	E0075	9515015377536	N/A	Not Classified	N/A	N/A	None
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0076	2590995933083	SL-3-11476A	No items classified sensitive	No equipment condition; however care should be taken around any and all electrical connections. SL-3 should remain with PEI.		No configuration differences
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0081	100501552693	NSN Replaced by 1005-01-575-2924	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0081	1005015752924	SAC-1, No SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0082	1240015751724	SL-3-11758A PCN 123 117580 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0083	2590015738437	N/A	NO	No Special Requirements		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0084	6650015593648	N/A	No/No/For SSRI Items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0085	6650015629944	SL-3 - 11576A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0086	1375982065633	N/A	N/A	Follow standard procedures	N/A	None
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0088	1240015780211	SL-3-11792A PCN 123 117920 00	No/No/For SSRI Items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0089	6695015602302	N/A	NO	Warning: Electrical Item		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0090	5865015623004	N/A	Dongle (sensitive) ship Per Fielding Plan	Follow standard procedures	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0091	5895014686173	N/A	Dongle (sensitive) ship Per ULSS	Follow standard procedures	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0094	1385013444429	N/A	N/A	Follow standard procedures	N/A	None
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0095	1240015715004	N/A	No/No/For SSRI Items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	Yes	E0096	7021015746985	SAC-1, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0100	1005015795325	SL-3 - 11810A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	Yes	E0103	1005015860114	SL-3 - 11920A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0104	4210014889655	SL-3-11871A	No items classified sensitive	No equipment condition. SL-3 should remain with PEI.		No configuration differences
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0105	7025-01-559-1217	SL-3-11791A(PCN 123 117910 00)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0106	4935-01-579-5013	SL-3-11811A(PCN 123 118110 00)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
13	MCS C-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	Yes	E0108	1265015585814	N/A	TAMCN is not classified. No classified SSRI or UURI.	No	This is the Army's configuration and is the laser only. Because it is a Class 3B laser, CONUS DMIL is required.	
13	MCS C-PMM-136	Donald Hooper	14-Nov; 1000 - 1500	Yes	E0108	1265015838057	No SL-3. Units may use TM 11902A-OI to ID SL-3 items.	TAMCN is not classified. No classified SSRI or UURI. TAMCN can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial).	No	This is the Marine Corps' configuration (kit). Because it is a Class 3B laser, CONUS DMIL is required.	No configuration differences.
Not Assigned	MCS C-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	E0113	9999010915096	N/A	TAMCN is not classified. No classified SSRI or UURI.	No/No wash down required		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0116	1010015862770	SL-3 - 11951A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0129	7610001305356	N/A	N/A	Follow standard procedures	This system will be replaced in FY13 once DSS MFK (E0772E) is fielded	None
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0139	6650010630035	SL-3 - 08552A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		

PG	PMM	MCS C POC for Reset Confirmation & ELM Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0139	6650015629886	SL-3 - 08552B	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0143	4920014905100	N/A	NO	No Special Requirements		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0144	1240010587460	SAC-1, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0149	5420005229599	SL-3-08940A/08942B	No items classified sensitive	No equipment condition. SL-3 should remain with PEI.		No configuration differences
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0150	5420008892020	SL-3-08940A/08942B	AVLB Launcher possesses communications gear and crew served weapons subject to appropriate treatment as per their own TAMCN	Armor deck (over powerpack) Removed. No high pressure wash in crew compartment and/or Exterior hydraulic cylinders. All SL-3 components removed for washdown/Agricultural Inspection. SL-3 should remain with PEI for shipment.		Only configuration differences pertain to communications gear addressed under the appropriate TAMCN
Not Assigned	MCS C-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	E0165	6130010189786		TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		T/E already established by CD&I
14	MCS C-PMM-141	Ssgt Robert Cole & Dell Murray	14-Nov; 1500 - 1730	No	E0180	6675010670687	SL-3-00476C	No, None	None	None	N/A
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E0190	1005013820953	SL-3 - 10012B	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0195	1005012310973	SL-3 - 10012A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS C-PMM-141	Ssgt Robert Cole & Dell Murray	14-Nov; 1500 - 1730	No	E0205	1240003321780	TM 8J813B-OD	No, None	Do not wash. Clean with damp cloth.	None	N/A
14	MCS C-PMM-141	Ssgt Robert Cole & Dell Murray	14-Nov; 1500 - 1730	No	E0205	1240014655452	TM 8J813B-OD	No, None	Do not wash. Clean with damp cloth.	None	N/A
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0207	1430015328900	Contained in EM 0183 (PCN 37909397100) and TM 09397D-OR (PCN 18409397700)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
16	MCS C-PMM-162	Michael Roberts	18-Nov; 0915 - 1415	No	E0210	1290009304260	SL-3-00477A				
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0260	1385011193324	N/A	N/A	Follow standard procedures	N/A	None
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0311	1005014586235	NSN REPLACED BY 1005-01553-5196	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0311	1005015535196	SL-3 - 11473A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
Not Assigned	MCS C-PMM-092	Stephen Magee	18-Nov; 1415 - 1500	No	E0312	1005013832949		TAMCN is not classified. No classified SSRI or UURI.	No		
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0330	5855013010158	SL-3-08554F (PCN 12308554500)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0359	1375010210606	OBSOLETE REPLACED BY NSN 1375014684400	N/A	NO	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0359	1375014684400	SL-3-10688A (TAMCN Discontinued. Component of B0471 Squad Demo Equip Set SL-3-00482B)	N/A	NO	N/A	None
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E0500	4933003488652	N/A	No, None	Do Not Spray or wet any Electronic Components	None	N/A
PEO LS	MCS C-PMM-LW155	Cynthia Sacca-Goodman	15-Nov; 1430 - 1600	No	E0671	1025014450991		No	No		
PEO LS	MCS C-PMM-LW155	Cynthia Sacca-Goodman	15-Nov; 1430 - 1600	No	E0671	1025994637551		No	No		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0720	1385996952988	TM 11124A-OR/4 Pg 12	N/A	Follow standard procedures	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0720	1385999911200	TM 11124A-OR/1 Pg 12, TM 11124A-OR/2 Pg 18, TM 11124A-OR/3 Pg 11-14	N/A	Follow standard procedures	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0759	1385012073619	N/A	N/A	Follow standard procedures	N/A	None
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0890	9999006911382	TAMCN IN DISPOSAL (DP)	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E0892	1010001796447	SL-3 - 07700B	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0915	1055011644608	SL-3-08673A (PCN SL-3-08673A)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.	Although this item is being replaced with a new version all launchers in theatre will need to be recovered as the new launcher is not in production yet.	
13	MCS C-PMM-133	Les Inbody	14-Nov; 1000 - 1500	No	E0935	1440014118942	SL-3-07722G (PCN 12307722600)	TAMCN is not classified. No classified SSRI.	Items are electronic and not environmentally sealed. Cleaning of the system should follow the procedures set forth in applicable TM.		

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0942	2355015393618		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08652B		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0946	2355014947611		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08650C		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0946	2355015393589		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08650C		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0947	2355014947606		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08594C (ITSS, E Drives)		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0947	2355015393639		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08594C (ITSS, E Drives)		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0948	2355015393634		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08654C		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0949	2355015393578		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08655C		
PM LAV	MCS C-PMM-LAV	CWO5 Ron Parks	15-Nov; 1300 - 1430	No	E0950	2355015393601		Yes: EKMS Radios and Weapon Systems (see Column G)	Per TM 08651B		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E0955	5855013984315	N/A	No/No/ N/A/Can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0956	5860014662087	SL-3-10471A PCN 123 104710 00 & SL-3-10471B PCN 123 104711 00	No/No/ For SSRI items, don't disassociate /Can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E0956	5860014712091	SL-3-10471A PCN 123 104710 00 & SL-3-10471B PCN 123 104711 00	No/No/ For SSRI items, don't disassociate /Can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0958	1385011360131	OBSOLETE REPLACED BY NSN 6665015037886	N/A	Follow standard procedures	N/A	None
15	MCS C-PMM-152	Mike Callahan	16-Nov; 0815 - 1700	No	E0958	6665015037886	N/A	N/A	Follow standard procedures	N/A	None
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0960	1005011277510	SL-3 -8671A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0961	1005012524288	Replaced by E0989, NSN: 1005-01-412-3129	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0980	1005007265636	SL-3 - 02498B	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0984	1005009573893	SL-3 - 02498C	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	Yes	E0989	1005014123129	SL-3 - 09712B	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0994	1010011269063	NSN Replaced by 1010-01-490-9697	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0994	1010014909697	SL-3 - 08521A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E0996	2590012308862	SL-3-09147A	Not Classified	N/A	N/A	None
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0998	1005010258095	SL-3 - 08670A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Staggars	14-Nov; 1000 - 1500	No	E0999	1005013626237	SL-3 - 09762A	TAMCN is not classified. No classified SSRI or UURI.	NO		
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1029	5860014124533	Obsolete	No, None	Do not wash. Clean with damp cloth.	None	N/A
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1030	5860070000768	Obsolete	No, None	Do not wash. Clean with damp cloth.	None	N/A
14	MCS C-PMM-141	Anthony Smith & Dell Murray	14-Nov; 1500 - 1730	No	E1035	6660014289218	SL-3-10269A	No, None	No direct water contact on electrical components	None	N/A
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1047	1240090001994	DP 10876A	No, None	Do not wash. Clean with damp cloth.	None	N/A

PG	PMM	MCS C POC for Reset Confirmation & ELMF Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1048	1240015615149	TM 11034A/11743A-OR	No	No Water	None	
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1048	1240015723753	TM 11034A/11743A-OR	No	No Water	None	
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1048	1240090003576	TM 11034A/11743A-OR	No	No Water	None	
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1048	1240090003759	TM 11034A/11743A-OR	No	No Water	None	
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1065	1010010205626	SL-3 - 08206A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS C-PMM-141	Bruce Weldon & Dell Murray	14-Nov; 1500 - 1730	No	E1070	1015015309102	TM 11166A-OR/1				
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1095	1015011646651	SL-3 - 09922A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1096	1005012540332	TAMCN IN DISPOSAL, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1120	1005007105599	NSN REPLACED BY 1005-01-433-1617	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1120	1005014331617	SAC-1, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E1123	1005013832949	NSN REPLACED BY 1010-01-502-7547	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E1123	1010011809319	NSN REPLACED BY 1010-01-502-7547	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E1123	1010014123159	NSN REPLACED BY 1010-01-502-7547	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	Yes	E1123	1010015027547	SAC-1, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1126	1005003229716	SAC-1, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1126	1005015030141	NSN REPLACED BY 1005-00-322-9716	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1126	1240006543811	NSN REPLACED BY 1005-00-322-9716	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
14	MCS C-PMM-141	Ssgt Robert Cole & Dell Murray	14-Nov; 1500 - 1730	No	E1145	1290014125760	Obsolete	No, None	Do not wash. Clean with damp cloth.	None	N/A
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1150	1005007012810	TAMCN IN DISPOSAL, NO SL-3	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E1152	5855014225413		No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	Yes	E1154	5855014320524	SL-3-10271A PCN 123 102710 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E1156	5855015264703		No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E1159	5855014228777	SL-3-07098B W/CH 1-2 00 PCN 123 070981 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		

PG	PMM	MCS C POC for Reset Confirmation & ELMP Pre Coordination	Date and Time Slot	UUNS	TAMCN	NSN	SL-3	Is the TAMCN itself classified sensitive? Are there any SSRI or UURI items that are classified sensitive? What are the procedures for disassociating these from the TAMCN? How should these items be packaged and shipped?	Is there any specific guidance needed to ensure a proper agriculture wash down is performed?	Other Amplifying Comments	SSRI & UURI Congruation to be fielded CONUS CD&I will refine this during the 13-15 Sept TAMCN by TAMCN review
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E1160	5855014916967	SL-3-10796C PCN 123 107962 00	No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
14	MCS C-PMM-142	CWO4 James Lee	14-Nov; 1500 - 1730	No	E1161	3655014469335	TM 10249A-14&P Appendix B		Ensure all lines are purged.		
13	MCS C-PMM-135	Joe Bernadoni	14-Nov; 1000 - 1500	No	E1162	5855014910140		No/No/For SSRI items, don't disassociate /can be shipped/transported by all means available to the Marine Corps, i.e., Ground (Truck), Air (Military and Commercial), and Maritime (Military and Commercial). This is an Optical Device, place in carrying case, w/ SSRI, batts removed. Reasonable care should be taken to protect the device from damage when packaged individually or in bulk.	No		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1205	1220015216088	SL-3 - 11042A	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		
13	MCS C-PMM-132	Wilson Stagers	14-Nov; 1000 - 1500	No	E1205	1220015540753	NSN REPLACED BY 1220-01-521-6088	TAMCN is not classified. No classified SSRI or UURI.	No specific Wash Down Equipment Conditions		